



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PD 546G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER (CONSISTENT)	DENTED	965.10	788.10
1	FRONT BUMPER SIDE HOLDER N/S (CONSISTENT)	CRACKED	166.50	162.50
1	SET FRONT BUMPER CLIPS (CONSISTENT)	NECESSARY	50.00	50.00
1	FRONT BUMPER BEAM (CONSISTENT)	BENT	655.20	615.30
1	FRONT BUMPER BEAM BRACKET N/S (CONSISTENT)	TO REPAIR SEE LABOUR	258.50	-
1	FRONT BUMPER TOP BEAM (CONSISTENT)	NOT NECESSARY	325.10	-
1	FRONT BUMPER FOG LAMP COVER N/S (CONSISTENT)	TWISTED	145.20	145.20
1	HEADLAMP N/S (CONSISTENT)	CRACKED	1,375.20	1,201.10
1	FRONT GRILLE OUTER CHROME ASSY (CONSISTENT)	CRACKED	1,280.00	650.00
1	FRONT GRILLE INNER (CONSISTENT)	CRACKED	785.10	645.20
1	FRONT CENTRE LOWER GARNISH (CONSISTENT)	TORN	322.50	282.50
1	FRONT DOOR N/S (CONSISTENT)	TO REPAIR SEE LABOUR	1,788.20	-
1	FRONT DOOR HINGE LOWER N/S (CONSISTENT)	NOT NECESSARY	95.00	-
1	FRONT DOOR INNER RUBBER N/S (CONSISTENT)	NOT NECESSARY	288.20	-
1	FRONT DOOR INNER TRIM BOARD N/S (CONSISTENT)	NOT NECESSARY	651.20	-
1	FRONT DOOR OUTER HANDLE N/S (CONSISTENT)	NOT NECESSARY	166.80	-
1	FRONT DOOR OUTER PILLAR N/S (CONSISTENT)	TO REPAIR SEE LABOUR	1,099.20	-
1	FRONT STEP GARNISH N/S (CONSISTENT)	NOT NECESSARY	341.50	-
1	FRONT STEP PANEL N/S (CONSISTENT)	NOT NECESSARY	488.90	-
1	FRONT WIRE HARNESS N/S (CONSISTENT)	NOT NECESSARY	650.50	-
1	FRONT WIRE HARNESS BRACKET N/S (CONSISTENT)	NOT NECESSARY	255.20	-
1	FRONT CORNER PANEL N/S (CONSISTENT)	NOT NECESSARY	466.10	-
1	SET FRONT DOOR 'ROC' STICKER N/S (CONSISTENT)	NOT NECESSARY	50.00	-
1	FRONT DOOR VISOR N/S (CONSISTENT)	NOT NECESSARY	80.00	-
	LESS 25% DISCOUNT		-	-1,134.98
			12,749.20	3,404.92
	<u>LABOUR</u>			
	TO CHECK WIRING.		50.00	20.00

Report Ref No. CC4/ASM22011336/Upa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SPRAY RUST PROOFING.	NOT NECESSARY	100.00	-
	TO TRANSFER FRONT DOOR MECHANISM .	NOT NECESSARY	100.00	-
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY .	NOT NECESSARY	180.00	-
	TO CONDUCT WHEEL ALIGNMENT.	NOT NECESSARY	100.00	-
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF FRONT BUMPER BEAM BRACKET N/S ,FRONT DOOR N/S AND FRONT DOOR OUTER PILLAR N/S .		1,280.00	500.00
	TO PUTTY & SPRAY PAINTING.		1,500.00	600.00
			3,310.00	1,120.00
GRAND TOTAL			16,059.20	4,524.92
RECOMMENDED COST OF REPAIRS				4,524.92

Report Ref No. CC4/ASM22011336/Upa3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.