



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:WINNIE			Ref: CC4/ASM22011336/Upa3q2 Date: 30/12/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SCW 260J	Veh. Inspected	PD 546G	
Policy No.	GA318316	Coverage (\$)	0.00	
Claim No.	S2M04EO5	Excess (\$)	0.00	
Assign From		Assign Date	11/11/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE HIGH ROOF COMMUTER(A)	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2022	
Chassis No.	JTFST22P900041157	Colour	WHITE	
Odometer	1739 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15	BRIDGESTONE	9 mm	
L/H Front Tyre	195 R15	BRIDGESTONE	9 mm	
R/H Rear Tyre	195 R15	BRIDGESTONE	9 mm	
L/H Rear Tyre	195 R15	BRIDGESTONE	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/11/2022	Inspection Date	11/11/2022	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	