

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT CS3/ASM22011337/Gnp3e2 AXA INSURANCE PTE LTD Ref: 8 SHENTON WAY #24-01 AXA TOWER Date: 23/12/2022 SINGAPORE 068811 ATTN: KHOR SAW THENG Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. **SHC 7388A** FBD 3551L Veh. Inspected Policy No. VFX/P2419140 Coverage (\$) 0.00 Claim No. S2M04EB0 Excess (\$) 0.00 KHOR SAW THENG **Assign Date** 11/11/2022 Assign From **Vehicle Particulars & Condition** 2. YAMAHA T135 c.c 135 Make & Model HIDDEN Engine No. Year of Reg. **BLACK** Chassis No. Colour Odometer Steering **IN ORDER IN ORDER** NIL **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 80/90-17 PIRELLI 5 mm L/H Front Tyre mm 80/90-17 DUNLOP R/H Rear Tyre 5 mm L/H Rear Tyre mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY. 5. **General Information** 04/11/2022 11/11/2022 (05:30 PM) Inspect Date / Time Accident Date KENG HOCK MOTOR Survey held at 188 YIO CHU KANG ROAD, SINGAPORE 545635 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000

Report Ref No. CS3/ASM22011337/Gnp3e2

Estimate Days of Repair

Inspected By

ESTIMATED NORMAL PERIOD FOR REPAIR:

5b.

XING GUO QIANG

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

2 Working Days

M.MATAI, AMSAE-A
Automotive Assessor