



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJB 3888G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER	DEFORMED	1,658.00	1,658.00
1	REAR BUMPER LOWER SPOILER	NOT NECESSARY	584.00	-
1	REAR BUMPER CHROME MOULDING	NECESSARY	214.00	214.00
1	REAR BUMPER SIDE RETAINER RH	DAMAGED	110.00	110.00
1	REAR BUMPER BRACKET RH	NOT NECESSARY	128.00	-
1	REAR FENDER RH	TO REPAIR SEE LABOUR	2,544.00	-
1	REAR FENDER AIR VENT RH	NOT NECESSARY	98.00	-
1	REAR FENDER INNER COWLING RH	NOT NECESSARY	322.00	-
1	REAR TAILLAMP LOWER BRACKET RH	CRACKED	87.00	87.00
1	RH REAR SHOCK ABSORBER	NOT NECESSARY	689.00	-
1	RH REAR LOWER ARM	NOT NECESSARY	562.00	-
1	RH REAR UPPER ARM	NOT NECESSARY	384.00	-
1	RH REAR KNUCKLE ARM	NOT NECESSARY	746.00	-
1	RH REAR KNUCKLE ARM BEARING	NOT NECESSARY	304.00	-
1	TAILLAMP	CRACKED	672.00	672.00
	LESS 10% DISCOUNT		-910.20	-274.10
			8,191.80	2,466.90
1	RH REAR WHEEL RIM (SN)	CUT	1,865.00	1,000.00
	LESS 10% DISCOUNT		-186.50	-
			1,678.50	1,000.00
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR BUMPER CLIPS (SN)	NECESSARY	80.00	30.00
1	RH REAR FENDER INNER COWLING CLIPS (SN)	NOT NECESSARY	60.00	-
			140.00	30.00
	<b><u>LABOUR</u></b>			
	LABOUR FOR PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR FENDER RH .		1,200.00	250.00
	LABOUR FOR SPRAYPAINTING.		1,000.00	500.00

Report Ref No. CS/AGI22011339/Avy3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	WIRING CHECK.		80.00	30.00
	LABOUR FOR REMOVE & REFIX REAR TAILGATE WINDSCREEN GLASS .	NOT NECESSARY	150.00	-
	TO APPLY TUFF COATING/RUST PROOF ACCIDENT AREAS.		200.00	30.00
	LABOUR FOR REMOVE & RENEW RH REAR UNDERCARRIAGE.	NOT NECESSARY	300.00	-
	TO CONDUCT WHEEL ALIGNMENT.		150.00	80.00
			3,080.00	890.00
<b>GRAND TOTAL</b>			<b>13,090.30</b>	<b>4,386.90</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,500.00</b>

Report Ref No. CS/AGI22011339/Avy3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.