



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 3035X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT DOOR O/S (CONSISTENT)	BENT / WARPED	941.00	941.00
1	FRONT DOOR INNER LOCK O/S (CONSISTENT)	NOT NECESSARY	288.50	-
1	SET FRONT DOOR FRAME BLACK STICKER O/S (CONSISTENT)	NECESSARY	60.00	60.00
1	REAR DOOR O/S (CONSISTENT)	TO REPAIR SEE LABOUR	955.00	-
1	SET REAR DOOR FRAME BLACK STICKER O/S (CONSISTENT)	NOT NECESSARY	60.00	-
1	SET REAR DOOR LOWER STICKER O/S (CONSISTENT)	NECESSARY	45.00	45.00
	LESS 20% DISCOUNT		-469.90	-209.20
			1,879.60	836.80
	<b><u>LABOUR</u></b>			
	TO CHECK WIRING.	NOT NECESSARY	50.00	-
	TO SPRAY RUST PROOFING.		60.00	30.00
	TO TRANSFER FRONT DOOR MECHANISM O/S.		80.00	50.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS. INCLUSIVE OF THE REPAIR OF REAR DOOR O/S.		480.00	200.00
	TO PUTTY & SPRAY PAINTING.		780.00	400.00
			1,450.00	680.00
	<b>GRAND TOTAL</b>		<b>3,329.60</b>	<b>1,516.80</b>

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>1,200.00</b>
---	--	--	-----------------

Report Ref No. CS/ASM22011342/Uqp3e2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.