

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBS 3732C

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT FENDER (CONSISTENT)	NOT NECESSARY	135.00	-
2	FORK TUNE ASSY - L/R (CONSISTENT)	NOT NECESSARY	980.00	-
1	FORK UNDER BRACKET (CONSISTENT)	NOT NECESSARY	285.00	-
1	FRONT SPORT RIM (CONSISTENT)	NOT NECESSARY	420.00	-
1	FRONT RIM SHAFT (CONSISTENT)	CUT	145.00	60.00
1	FRONT RIM BEARING (CONSISTENT)	NOT NECESSARY	105.00	-
1	FRONT BRAKE DISC (CONSISTENT)	NOT NECESSARY	235.00	-
1	WINDSHIELD (CONSISTENT)	CRACKED	385.00	190.00
1	HANDLE-BAR (CONSISTENT)	BENT	385.00	240.00
1	SET HANDLE-BAR END (CONSISTENT)	CUT	155.00	40.00
1	SET HAND GRIP (CONSISTENT)	NOT NECESSARY	95.00	-
1	SET SIDE MIRROR (CONSISTENT)	BROKEN	180.00	80.00
1	SET CLUTCH LEVER (CONSISTENT)	NOT NECESSARY	190.00	-
1	SET FRONT SIGNAL (CONSISTENT)	O/S CUT	140.00	70.00
1	METER ASSY (CONSISTENT)	CRACKED	685.00	685.00
1	METER COVER (CONSISTENT)	CRACKED	185.00	115.00
1	HEADLAMP COVER (CONSISTENT)	CUT	185.00	185.00
1	FUEL TANK SIDE COVER - R/H (CONSISTENT)	CUT	255.00	148.00
2	FRONT FOOTREST (CONSISTENT)	O/S BENT	180.00	60.00
2	FRONT FOOTREST BRACKETS (CONSISTENT)	O/S BENT	450.00	142.00
1	BRAKE PEDAL (CONSISTENT)	BENT	135.00	135.00
1	EXHAUST ASSY (CONSISTENT)	TO REPAIR SEE LABOUR	1,450.00	-
1	EXHAUST PROTECTOR (CONSISTENT)	TORN	168.00	168.00
1	EXHAUST END COVER (CONSISTENT)	CUT	78.00	60.00
2	REAR FOOTRESTS (CONSISTENT)	O/S CUT	180.00	60.00
2	REAR FOOTREST BRACKETS (CONSISTENT)	NOT NECESSARY	480.00	-
1	REAR SIDE COVER - R/H (CONSISTENT)	CUT	285.00	168.00
1	REAR FENDER (CONSISTENT)	NOT NECESSARY	170.00	-
	LESS 10% DISCOUNT		-872.10	-260.60
			7,848.90	2,345.40

Report Ref No. CS/ASM22011343/Unp3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

2,350.00

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	SPECIAL NETT ITEMS			
1	NUMBER PLATE (SN) (CONSISTENT)	FRONT NECESSARY	38.00	10.00
2	FORK OILS (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
2	FORK OIL SEALS (SN) (CONSISTENT)	NOT NECESSARY	56.00	-
1	SET STEERING CONE (SN) (CONSISTENT)	NOT NECESSARY	95.00	-
1	E.R.P. IU (SN) (CONSISTENT)	DAMAGED	180.00	165.00
1	SLIDER (SN) (CONSISTENT)	NECESSARY	380.00	80.00
1	SET MT-15 STICKER (SN) (CONSISTENT)	NECESSARY	150.00	50.00
			929.00	305.00
	<u>LABOUR</u>			
	TO REMOVE, REFIT AND ALIGN BODY FRAME.	NOT NECESSARY	420.00	-
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.	NOT NECESSARY	80.00	-
	TO PROVIDE LABOUR. INCLUSIVE OF THE REPAIR OF EXHAUST ASSY.		400.00	300.00
			900.00	300.00
	GRAND TOTAL		9,677.90	2,950.40

Report Ref No. CS/ASM22011343/Unp3e2

RECOMMENDED COST OF LUMP SUM REPAIRS

(TO ITS PRE-ACCIDENT CONDITION)

CHUA KANG SENG

Licensed Appraiser