



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBD 840Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT HEADLAMP COMPLETE ASSY	NOT NECESSARY	675.50	-
1	FRONT HEADLAMP OUTER COWLING	CUT	185.30	185.30
1	MIRROR ASSY LH	CUT	167.20	167.20
1	FRONT CLUTCH LEVER LH	CUT	276.20	276.20
1	FRONT HANDLE BAR	BENT	295.00	295.00
2	FRONT HANDLE BAR GRIP @\$62.80	NOT NECESSARY	125.60	-
1	SET FRONT FORK ASSY	BENT	2,262.50	1,000.00
1	FRONT FENDER	CUT	185.00	185.00
1	FRONT BRAKE DISC	BENT	325.20	325.20
1	FRONT WHEEL RIM	NOT NECESSARY	574.30	-
1	FRONT SIDE STAND	NOT NECESSARY	125.40	-
1	FRONT SIGNAL LH	NOT NECESSARY	136.20	-
1	FRONT SIDE FAIRING LH	CUT	243.60	243.60
1	REAR SIDE TOP FAIRING LH	CUT	217.40	217.40
2	FRONT WHEEL BEARING @\$25.00	NECESSARY	50.00	50.00
1	PILLION FOOT REST LH	NOT NECESSARY	167.40	-
1	REAR LEFT SIDE COWLING COVER	DEFORMED	195.00	195.00
2	REAR SIGNAL LAMP LH @\$145.00	O/S NOT NECESSARY / N/S CRACKED	290.00	145.00
2	FRONT INNER COWLING LH @\$252.60	DEFORMED	505.20	505.20
1	FRONT FORK STEM	NOT NECESSARY	376.40	-
1	FRONT NUMBER PLATE	NECESSARY	30.00	30.00
	LESS 10% DISCOUNT		-740.84	-382.01
			6,667.56	3,438.09
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRONT FORK OIL (SN)	NECESSARY	45.00	45.00
1	FRONT RIM (SN)	DENTED	570.30	480.00
1	STICKERS (SN)	NECESSARY	153.00	153.00
1	HELMET (SN)	CRACKED	565.80	450.00
			1,334.10	1,128.00

Report Ref No. CS/AGI22011347/Tvy3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>LABOUR</u></b>			
	WORKMANSHIP.		600.00	300.00
	SPRAY PAINTING.		600.00	200.00
	ELECTRICAL.		80.00	30.00
	FRONT WHEEL ALIGNMENT.		50.00	30.00
			1,330.00	560.00
<b>GRAND TOTAL</b>			<b>9,331.66</b>	<b>5,126.09</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>4,000.00</b>

Report Ref No. CS/AGI22011347/Tvy3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.