

# J&M CONSULTANCY PTE LTD

11 Changi South Lane #02-08  
ONN WAH BUILDING Singapore 486154  
Company Reg No: 202125502E  
Tel: 6214-0474 Fax: 6384-5205

## VEHICLE INSPECTION REPORT

To: CHAI CHIANG WOON

Date : 26 August 2022

C/o: A-Tec Automotive Pte Ltd  
8 Kaki Bukit Avenue 4  
#04-20 Premier @ Kaki Bukit, Singapore 415875

Our ref : ATEC/08/0045/JM

Accident Date : 19 April 2022

Type of Survey : Third party

Inspection Date : 25 April 2022

Repairer Name : A-Tec Automotive Pte Ltd

8 Kaki Bukit Avenue 4

#04-20 Premier @ Kaki Bukit, Singapore 415875

### PARTICULARS OF VEHICLE

Registration No : SJM 2387 J

Year / Capacity : 2008 / 1399cc

Make / Model : Chevrolet/ Chevy Aveo

Colour : Silver

Chassis No : KL1SA69719B619018

Mileage : 140,098 km

Engine No : F14D37337771

### CONDITION OF TYRES

	Make	Size	Thread Balance
Front Nearside	: Tourador	185/60 R14	80%
Front Offside	: Tourador	185/60 R14	80%
Rear Nearside	: Tourador	185/60 R14	80%
Rear Offside	: Tourador	185/60 R14	80%

### GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the rear bumper portion.

*(Details refer to the photographs attached)*

Enclosed number of photographs: 47 copies

### REMARKS

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis and we have not given authorization and instruction to the repairer to proceed with the repair.

Vehicle Registration No: SJM 2387 J

Our Ref No: ATEC/08/0045/JM

**RECOMMENDATIONS**

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

Under normal circumstances, the repair period would be about **7( Seven )** working days.

Qty	Description	Condition	Repairer's Estimate	Revised Amount
-----	-------------	-----------	---------------------	----------------

**SPARE PARTS - LIST ITEMS**

1	Rear bumper assy	Warped/Dented	\$ 1,200.00	\$ 1,200.00
1	Rear bumper retainer (1 set )	Warped/Necessary	\$ 350.00	\$ 350.00
1	Rear bumper bracket ( 1 set )	Warped/Necessary	\$ 380.00	\$ 380.00
1	Rear bumper reflector ( 1 set )	Cracked	\$ 470.00	\$ 470.00
1	Rear bumper reinforcement bracket (1 set )	Cracked	\$ 580.00	\$ 580.00
1	Rear bumper top garnish	Warped	\$ 520.00	\$ 520.00
1	Rear bumper weatherstrip	Warped/Necessary	\$ 380.00	\$ 380.00
1	Rear tailgate assy	Repair	\$ 1,350.00	\$ -
1	Rear tailgate lock catch w actuator	Bent	\$ 550.00	\$ 550.00
1	Rear taillamp LH	Cracked	\$ 1,100.00	\$ 1,100.00
1	Rear taillamp RH	Cracked	\$ 1,100.00	\$ 1,100.00
1	Rear exhaust pipe muffler	Bent	\$ 680.00	\$ 680.00
1	Rear end panel assy	Warped	\$ 720.00	\$ 720.00
Total			\$ 9,380.00	\$ 8,030.00
Less 10%			\$ 938.00	\$ 803.00
			<b>\$ 8,442.00</b>	<b>\$ 7,227.00</b>

**SPECIAL NETT ITEMS**

1	Rear bumper clips ( 1 set )	Necessary	\$ 100.00	\$ 100.00
1	Rear bumper reverse sensor ( 1 set )	Malfunction	\$ 650.00	\$ 650.00
1	Rear end panel sealant ( 1 set )	Necessary	\$ 120.00	\$ 120.00
Total			\$ 870.00	\$ 870.00
<b>Total parts</b>			<b>\$ 9,312.00</b>	<b>\$ 8,097.00</b>

Vehicle Registration No: SJM 2387 J

Our Ref No: ATEC/08/0045/JM

S/No	Description	Repairer's Estimate	Revised Amount
Total cost of parts c/f		\$ 9,312.00	\$ 8,097.00
<b><u>LABOUR</u></b>			
1	To cut, weld, straighten affected areas and replace damaged parts.	\$ 2,400.00	\$ 2,000.00
2	To putty and spray painting the affected areas. Job Allowance.	\$ 2,400.00	\$ 2,000.00
3	To check rear lighting and wiring.	\$ 280.00	\$ 260.00
4	To apply anti rust proofing to the affected areas.	\$ 300.00	\$ 280.00
5	To remove and install rear bumper assy.	\$ 280.00	\$ 260.00
6	To remove and install garnish and trim to facilitate the repair	\$ 280.00	\$ 260.00
7	To remove and install taillamps.	\$ 280.00	\$ 260.00
8	To remove and install exhaust muffler pipe.	\$ 280.00	\$ 260.00
9	To remove and install tailgate assy.	\$ 280.00	\$ 260.00
10	To remove and install lock mechanism.	\$ 280.00	\$ 260.00
11	To conduct central lock system.	\$ 300.00	\$ 280.00
12	To remove and install rear bumper reverse sensor	\$ 280.00	\$ 260.00
13	To conduct chassis alignment.	\$ 300.00	\$ 280.00
<b>Grand Total:</b>		<b>\$ 17,252.00</b>	<b>\$ 15,017.00</b>

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : \$ 12,000**

Vehicle Registration No: SJM 2387 J

Our Ref No: ATEC/08/0045/JM

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within (7) from the date hereof. Otherwise, the revised amount shall be deemed to be valid.

**Disclaimer**

*The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.*

**J&M Consultancy Pte Ltd**



**Joel Liew Jian Xiang**  
**Automotive Appraiser**













































