

APPRAISAL SERVICES

220A Sumang Lane #06-75 (S)821220 Tel: 9101 7844 Fax: 6996 6442 Business Reg. No.:

Email: dylanlee.as @gmail.com

Automotive Inspection, Evaluation & Consultation

Our Reference: TP/2205/FBR5266Z/CKM

M/S Business Integrator Pte Ltd

Bill No.: LA22060003

C/O Goh JP & Wong LLC

Bill Date: 03 Jun 2022

133 New Bridge Road #16-09 Chinatown Point Singapore 059413

To our services rendered in connection with the below matters:-

<u>Description</u>		<u>Amount</u>
Survey fees	\$	280.00
Transportation	\$	180.00
Photographs (71) Copies	\$	71.00
To	otal: \$	531.00

Dollars: Five Hundred And Thirty One Only.

Please quote our Bill No. or return a copy of our bill with your remittance. Cheque should be made payable to "Lee Appraisal Services", or via PayNow Corporate to UEN "53387981K".

LEE APPRAISAL SERVICES

Lee Kah Pang

Dip Mech Engr, BCompSc

APPRAISAL SERVICES

220A Sumang Lane #06-75 (S)821220 Tel: 9101 7844 Fax: 6996 6442

Business Reg. No.: 53387981K Email: dylanlee.as @gmail.com

Automotive Inspection, Evaluation & Consultation

Our Reference: TP/2205/FBR5266Z/CKM

VEHICLE APPRAISAL REPORT

M/S Business Integrator Pte Ltd

03 Jun 2022 Report Date:

C/O Goh JP & Wong LLC 133 New Bridge Road #16-09 Chinatown Point Singapore 059413

REFERENCE

Your Reference No.:

GTW.ACC.5047.22

Date of Inspection

25 May 2022

Type of Appraisal: Date of Accident

Third Party : 12 May 2022 Date of Re-inspection 1 : Date of Re-inspection 2 : 01 Jun 2022

26 May 2022

PARTICULARS OF VEHICLE

Registration No. Make

FBR5266Z

First Reg Date:

30 Jul 2020

Model

Yamaha

COE Expiry :

29 Jul 2030 41797

:

Color

MX King T150

Odometer Engine No.

G3E6E0589782

Manufacturing Year: 2020

Red

Chassis No.

MH3UG0750LK071227

CONDITIONS OF VEHICLE (STATIC CHECK AT TIME OF INSPECTION ONLY)

Front Brake:

Serviceable

Steering

Damaged

Rear Brake:

Serviceable

Modification:

None

TYRE / CONDITION

Location

Make & Size

Thread

Front Rear

Dunlop 90/80-17 Dunlop 120/70-17 4 mm 5 mm

DAMAGE PROFILE

The vehicle sustained damages on front & both sides. The body frame steering column was damaged.

Please refer to photographs and assessment of repairs for details.

ASSESSMENT SUMMARY

Repair cost to the vehicle is assessed as \$3,600.00 on lump sum basis

Estimated period required for repairs: (6) days

This vehicle has a net value of about \$5,592.00 at the time of survey.

Survey conducted at: Chek Kong Motor Pte Ltd

Enclosed (71) photographs depicting damages to the vehicle

The survey was conducted on a WITHOUT PREJUDICE basis.

LEE APPRAISAL SERVICES



220A Sumang Lane #06-75 (S)821220 Tel: 9101 7844 Fax: 6996 6442 Business Reg. No.:

53387981K

Email: dylanlee.as @gmail.com

Loss Adjuster, Automotive Inspection, Evaluation & Consultation

Our Reference: TP/2205/FBR5266Z/CKM

ASSESSMENT FOR REPAIR: FBR5266Z

			Repairer's	<u>Our</u>	
Qty	Description	Condition	Estimate	Assessment	
1 pc	Handle bar	Bent	85.00	85.00 ✓	
1 set	Handle bar end	Cut	40.00	40.00 🗸	
1 pc	Clutch lever	Usable	28.00	~X nn	
1 pc	Brake lever	Cut	28.00	28.00 🗸	
1 set	Mirror	Broken	96.00	96.00 45 🗸	
1 pc	Front cowling complete	Grazed	165.00	165.00 🗸	
1 pc	Front inner panel	Cut	116.00	116.00 🗸	
1 pc	Front stay	Distorted	65.00	65.00 🗸	
1 set	Fork assy	Bent	760.00	760.00 700 ✓	
1 pc	Fork under bracket	Bent	165.00	165.00 🗸	
1 pc	Front fender complete	Cut	122.00	122.00 🗸	
1 pc	Radiator assy	Dented	415.00	415.00 ★ nn	
2 pcs	Front side cover complete @148.00	RH Cut	296.00	148.00 🗸	
1 pair	Front signal light	RH Cut	112.00	112.00 🗸	
1 pc	Gear shift pedal	Usable	59.00	∼× nn	
1 pc	Brake pedal	Cut / Bent	62.00	62.00 🗸	
2 pcs	Rear cover complete @128.00	Cut / Grazed	256.00	256.00 🗸	
1 pc	Rear fender complete	Bent	126.00	126.00 🗸	
1 set	Rear fender bracket	Bent	42.00	42.00 × nn	
1 pc	Muffler assy	Cut	485.00	485.00 🗸	
1 pc	Muffler protector	Cut	72.00	72.00 60 ✓	
1 pc	Muffler cap	Cut	42.00	42.00 35 	
			3,637.00	3,402.00 2815	
		Less 10%	363.70	340.20 -10%	
			3,273.30	3,061.80 2533.50	
				2000.00	
	Special Nett Items				
1 set	Steering cone & bearing	Necessary	80.00	60.00 🗸	
1 btl	Radiator coolant	Necessary	24.00	24.00 X nn	
			104.00	84.00	
	Total Parts		3,377.30	<u>3,145.80</u> 60	
	Labour Charges				
1	Towing fee		80.00	60.00 🗸	
2	Repair body frame steering column		700.00	650.00 200	
3	Repair & straighten swingarm		300.00	250.00 100	
4	Renew damaged parts & repair affected areas		450.00	400.00 300	
		250.50	1,530.00	1,360.00	
	A days 3	253 50			

4 days

3253.50

660

LEE APPRAISAL SERVICES

220A Sumang Lane #06-75 (S)821220
Tel: 9101 7844 Fax: 6996 6442

Business Reg. No.: 53387981K Email: dylanlee.as @gmail.com

Adjuster, Automotive Inspection, Evaluation & Consultation

Our Reference: TP/2205/FBR5266Z/CKM

Total Parts & Labours Concluded

4,907.30

4,505.80

Lump Sum Repair Adjustment

3,600.00

ADJUSTMENT/RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damages found on the vehicle. We have listed the breakdown of our findings and our recommendations as per assessment above.

Yours faithfully, LEE APPRAISAL SERVICES

Lee Kah Pang

Dip Mech Engr, BCompSc