LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI22004927/RQY3N2

Date: 02/06/2022

REFERENCE

China Taiping

Handling Insurer: Insurance (Singapore) P

(Singapore) Pte.

Policy No: DMCVSNW00116512100

₋td.

Claimant Vehicle

Date of Loss:

Insured

FBR5266Z

12/05/2022

Vehicle No GBB6739D

Nature of TP Claim:

Claim

Odometer:

No. SNM22D203308/C02/IRENE

41797 km

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBR5266Z

 Make & Model:
 YAMAHA MX KING T150, 150cc
 Engine No:
 G3E6E0589782

 Reg. Date:
 30/07/2020 (Man. Year: 2020)
 Chassis No:
 MH3UG0750LK071227

Colour: Multi-colour

Engine Capacity: 150 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 90/80-17 Rear Tyre Size: 120/70-17
Front Left Side: Dunlop 3 mm Rear Left Side: Dunlop 3 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		0.00	0.00	0.00	
Miscellaneous Items		0.00	0.00	0.00	
Labour		0.00	0.00	0.00	
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 25/05/2022

Chek Kong Motor Pte Ltd (HQ)

Date Inspected: 25/05/2022 Inspected At: BLK 1 387B WOODLANDS ROAD, YEW TEE INDUSTIRL

ESTATE

Singapore 677948

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 -\$3,000.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 01 Jun 2022)

YAMAHA MX KING T150 150cc (Model not available in database) Parts: N/A

Labour: (Price-denominated Standard List) Repairer's

Print Code: LKK Auto Consultants Pte Ltd/FBR5266Z/02/06/2022 16:18

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page Validity:

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

LKK Auto Consultants Pte Ltd/FBR5266Z/02/06/2022 16:18. Not valid without Reference section.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

LKK Auto Consultants Pte Ltd/FBR5266Z/02/06/2022 16:18. Not valid without Reference section.

< END OF ESTIMATES >