

**AB ENGINEERING PTE LTD**

10 Kaki Bukit Road 2 #01-25

First East Centre ,Singapore 417868

Tel No : 6513 1700 / 88586282

UEN/GST : 202117273R

Bill To :

**AXA Insurance**

9 North Buona Vista Drive

#18-01/06, Tower 1 The Metropolis,

Singapore 138588

**PROFORMA INVOICE**

Phone : 65 6880 4888

Attention : Claim Dept

Invoice :	PF22110001
Date :	8-Nov-22

Vehicle No	Terms
SMZ9699J	C.O.D
Description	Amount (\$\$)
<b>Parts</b> Headlamp assy - LH Front bumper Front bumper retainer - LH Front bumper clip Front bumper cover - LH Front bumper lower skirt - LH Front bumper lip - Center Front fog lamp - LH Fog lamp garnish - LH Front fog lamp moulding chrome - LH Front fender arch - LH Front fender arch clip - LH Air guide - LH Cornering Lamp - LH Front sensor - LH Headlamp Nozzle - LH Fog Lamp Bracket - LH Front bumper sponge  To dismantle damaged parts; to heat/weld, cut-off the front bonnet, front bumper, front fender LH, front chassis frame LH, including replacement of parts and align where necessary, to refit and adjust of same.  To putty and spray paint (premium) on affected areas.  To apply rust-proofing on replaced and repaired panels.  To diagnose and calibrate front sensor wiring system, safety systems, parking aid sensors & re-set of same.  To diagnose re-calibrate adaptive front lighting system (Lexus triple-beam led headlamps), with a suite sensors & re-set of same.	
<b>TOTAL REPAIR AND LABOUR CHARGES AS FINALISED WITH SURVEYOR(Exclusive gst) :</b>	<b>\$ 11,661.42</b>

**Memo :**

Please make payment to AB Engineering Pte Ltd via

Transfer to DBS Bank Acc : 0720400712

Paynow : 202117273R

Your early settlement is appreciated.

**AB ENGINEERING PTE LTD**