

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22011351/EQY3Q2**Date:** 08/12/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00093012201	
Claimant Vehicle No :	PA6567Y	Insured Vehicle No :	GBC9640D	
Date of Loss:	29/10/2022	Nature of Claim:	TP	Claim No: SNM22D207827/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PA6567Y		Engine No:	6HK1433711
Make & Model:	ISUZU LT134P, 7.8 D (M)		Chassis No:	JALLT134P67000085
Reg. Date:	26/09/2006 (Man. Year: 2006)		Odometer:	337894 km
Colour:	Multi-colour			
Engine Capacity:	7790 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	285/80 R22.5	Rear Tyre Size:	285/80 R22.5
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,917.00	5,277.50	2,639.50	33.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,800.00	2,200.00	2,600.00	54.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,717.00	7,477.50	5,239.50	41.20
Approved Total (Overridden) (S\$)		6,000.00		
Nett Amount (S\$)	12,717.00	6,000.00	6,717.00	52.82

INSPECTION

Date of Assignment:	14/11/2022	SERVE YOU MOTOR PTE LTD (HQ) BLK 5033 ANG MO KIO INDUSTRIAL PARK 2, #01-265 Singapore 569536
Date Inspected:	07/11/2022 Inspected At:	
Estimated Period of Repair:	4.0 days	

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 08 Dec 2022)	
Parts:	N/A	ISUZU LT134P 7.8 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PA6567Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	2,950.00 FL	*2,600.00 FL
2	1		*REAR PANEL INNER BRACKETS	Repair	1,100.00 FL	*- FL
3	1		*BUMPER BEAM	Repair	550.00 FL	*- FL
4	1		*REAR TAILGATE	Dented	3,760.00 FL	*3,550.00 FL
5	1		*STICKER LOGO	Necessary	80.00 FS	*50.00 FS
6	1		*REAR TAILGATE LOCK	Not Necessary	228.00 FS	*- FS
7	1		*REAR HANDLE	Not Necessary	85.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,753.00	6,200.00
- List Item Discount on L Items 10.00/15.00% (\$\$)	836.00	922.50
Total Parts (\$\$)	7,917.00	5,277.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK OUT THE ACCIDENT DAMAGED PORTION .TO PANEL BEATING ,RESHAPE ,STRAIGHTEN ,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	2,200.00	900.00
2	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY ON THE ACCIDENT DAMAGE AREA AND OTHER AFFECTED AREA /PANEL	New	2,200.00	950.00
3	TO SPRAY UNDER-CARRIAGE INSULATION FOAM	New	400.00	350.00
Gross Labour Cost (S\$)			4,800.00	2,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >