

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22011354/AYA3Q2**Date:** 18/02/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100475449
Claimant Vehicle No :	SLW5773G	Insured Vehicle No :	SLE4202P
Date of Loss:	28/10/2022	Nature of Claim:	TP
		Claim No:	4429429294SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLW5773G	Engine No:	2NRX281418
Make & Model:	TOYOTA SIENTA, 1.5 (A)	Chassis No:	MHFZ28H3800051216
Reg. Date:	22/02/2018 (Man. Year: 2018)	Odometer:	123921 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/50 R16	Rear Tyre Size:	205/50 R16
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,137.20	5,762.27	6,374.93	52.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,500.00	1,740.00	760.00	30.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	14,637.20	7,502.27	7,134.93	48.75
Approved Total (Overridden) (\$\$)		6,000.00		
Nett Amount (\$\$)	14,637.20	6,000.00	8,637.20	59.01
+ Car Rental (6.0 x S\$100.00/day) (\$\$)		600.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		6,607.45		

INSPECTION

Date of Assignment:	07/11/2022		
Date Inspected:	07/11/2022	Inspected At:	YSK Auto Workshop (HQ) 1 Kaki Bukit Avenue 6 @ AutoBay, #01-71 Singapore 417883
Estimated Period of Repair:	6.0 days		

Adjuster: ADRIAN LING**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	486.10 F	*486.10 FL
2	1		*FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
3	1		*FRONT BUMPER SIDE HOLDER RH	Damaged	48.10 F	*48.10 FL
4	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	330.90 F	*- FL
5	1		*FRONT BUMPER SPONGE	Not Necessary	145.10 F	*- FL
6	1		*FRONT BUMPER FOG LAMP RH	Cracked	276.40 F	*276.40 FL
7	1		*FRONT BUMPER FOG LAMP COVER RH	Cut	108.50 F	*108.50 FL
8	1		*HEADLAMP RH	Cracked	3,050.10 F	*3,050.10 FL
9	1		*FRONT RH FENDER	Dented	713.20 F	*713.20 FL
10	1		*FRONT RH FENDER INNER SHIELD	Deformed	216.70 F	*216.70 FL
11	1		*FRONT RH FENDER INNER SHIELD CLIPS	Necessary	30.00 FS	*30.00 FS
12	1		*FRONT RH TYRE	Not Necessary	250.00 FS	*- FS
13	1		*FRONT RH WHEEL RIM	Cut	880.00 FS	*550.00 FS
14	1		*SLIDING DOOR RH	Repair	1,217.50 F	*- FL
15	1		*SLIDING DOOR PROTECTOR RH	Cut	198.80 F	*198.80 FL
16	1		*REAR RH FENDER PROTECTOR RH	Cut	101.90 F	*101.90 FL
17	1		*FRONT RH LOWER ARM	Bent	486.30 F	*486.30 FL
18	1		*FRONT RH SHOCK ABSORBER	Bent	407.40 F	*407.40 FL
19	1		*FRONT RH KNUCKLE ARM	Damaged	425.40 F	*425.40 FL
20	1		*FRONT RH WHEEL HUB C/W BEARING	Damaged	350.80 F	*350.80 FL
21	1		*STEERING RACK AND PINION	Not Necessary	2,384.00 F	*- FL
					Sub Total (\$\$)	12,137.20 7,479.70
					- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00 1,717.43
					Total Parts (\$\$)	12,137.20 5,762.27

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	800.00	650.00
2	SPRAY PAINTING	New	800.00	700.00
3	WIRING	New	100.00	30.00
4	TO SPRAY TUFF COAT	New	150.00	60.00
5	TO TRANSFER SLIDING DOOR FITTINGS	New	150.00	0.00
6	TO DISMANTLE FRONT UNDERCARRIAGE	New	350.00	220.00
7	TO PERFORM WHEEL ALIGNMENT	New	150.00	80.00
Gross Labour Cost (\$\$)			2,500.00	1,740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >