

PRUDENT ADJUSTORS SERVICES

BLOCK 607 ELIAS ROAD #05-192

SINGAPORE 510607

BUSINESS REGN. No. 53193457L

HP: 96699986

VEHICLE DAMAGE INSPECTION REPORT

Mr Chan Bo Rui
Block 253 Tampines Street 21 #11-406
Singapore 521253

Our Ref : PA/FBM267/0120/tpw
Date : 24 September 2020

REFERENCES

Claim Type	: Third Party	Date of Accident	: 21 January 2020
Vehicle No.	: FBM 267 E	Date of Assignment	: 23 January 2020
Make	: Kawasaki	Date of Inspection	: 23 January 2020
Model	: Z1000 ABS Manual	Date of Re-inspection	: 01 April & 10 September 2020
Reg. Date	: 14 June 2017	COE Expiry	: 13 June 2027
Color	: Black	Chassis No	: JKAZRT00HJA001465
Odometer	: No Key	Engine No	: Blocked

TYRE CONDITION

	<u>Make</u>	<u>Size</u>	<u>Thread Balance</u>
Front	Michelin	120/90-17	5mm
Rear	Michelin	190/50-17	6mm

GENERAL DESCRIPTION OF DAMAGE (PHOTOGRAPHS ATTACHED)

The vehicle sustained damage at front and both sides.
Please refer to photographs and assessment of repairs for details
Enclosed (66) photographs depicting damage and after repaired

INSPECTION AND ADJUSTMENT

Original Quotation : \$23,629.39 Revised Assessment : \$18,000.00 Lump sum

Survey conducted at Revology Bikes Pte Ltd

In accordance to your instruction, we have not authorized repairs.

In normal circumstances, repairs to the vehicle would take approximately
Ten (10) days to complete.

This survey was conducted on a "WITHOUT PREJUDICE" basis.

Note:

The workshop has agreed to undertake the repair on a lump sum basis, and or the use of ex-stock
Reconditioned parts whichever is possible

PRUDENT ADJUSTORS SERVICES

Vehicle No: FBM 267 E

Our Ref : PA/FBM267/0120/tpw

ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS

<u>S/N</u>	<u>Description</u>	<u>Qty</u>	<u>Condition</u>	<u>Original Quotation</u>	<u>Revised Quotation</u>
1	Front upper cowling	1 pc	Cut	363.40	363.40
2	Center cowling	1 pc	Cut	127.10	127.10
3	Front lower cowling	1 pc	Cracked	170.40	170.40
4	Handle bar	1 pc	Bent	478.70	478.70
5	Handle bar end	1 set	Cut	80.00	80.00
6	Mirror assy	1 set	Cut	380.00	380.00
7	Brake lever	1 pc	Broken	120.50	120.50
8	Clutch lever	1 pc	Bent	95.80	95.80
9	Head lamp complete	1 pc	Cracked	3,250.00	3,250.00
10	Fork top bridge	1 pc	Distorted	540.00	540.00
11	Fork assy @ \$1854.70/-	2 pcs	Leak / Bent	3,709.90	3,709.90
12	Fork under bracket	1 pc	Bent	878.20	878.20
13	Front signal lamp @ \$126/-	2 pcs	Broken/cut	252.00	252.00
14	Front fender	1 pc	Cut	322.30	322.30
15	Front wheel assy	1 pc	Warped	1,576.90	1,576.90
16	Front brake disc plate @ \$514/-	2 pcs	Warped	1,028.00	1,028.00
17	Fuel tank front cover	1 pc	Usable	488.50	~
18	Fuel tank	1 pc	Dented	1,868.00	1,868.00
19	Side cowling @ \$644.30/-	2 pcs	Cut	1,288.60	1,288.60
20	Side cowling slat @ \$272.60/-	2 pcs	Torn / Cut	545.20	545.20
21	Side inner cowling @ \$92.30/-	2 pcs	Deformed	184.60	184.60
22	Swing arm	1 pc	Dented/bent	2,925.00	2,925.00
23	Exhaust muffler	1 pc	Dented	2,704.00	2,704.00
				23,377.10	22,888.60
	List price less 10%			2,337.71	2,288.86
				21,039.39	20,599.74
	<u>Special nett item</u>				
24	Front number plate	1 pc	Necessary	20.00	18.00
25	Steering cone & bearing	1 set	Necessary	380.00	190.00
26	Front wheel bearing	1 pc	Necessary	120.00	60.00
27	Body sliders	1 set	Cut	250.00	220.00
28	Swing arm bushes	1 set	Necessary	210.00	105.00
				980.00	593.00
	<u>Labour Charges</u>				
	Towing fee (2 trips)			160.00	150.00
	Repair and straight body frame			650.00	600.00
	Workmanship to repair & renew damaged areas			800.00	600.00
				1,610.00	1,350.00

PRUDENT ADJUSTORS SERVICES

Vehicle No: **FBM 267 E**

Our Ref : PA/FBM267/0120/tpw

Total parts & labours concluded	<u>23,629.39</u>	<u>22,542.74</u>
Lump sum repair adjustment		<u>18,000.00</u>

The information contained in this document is privileged and confidential and is intended for the exclusive use of the addressee designation. If you are not the addressee; any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this document not meant for you, please contact us immediately to arrange for it to return.



Prudent Adjustors Services
Bok Jee Tan