A-PAC Adjusters & Surveyors Pte Ltd (Co.Reg.No:201705143H) 28 Sin Ming Lane, #06-141 Midview City Singapore 573972 Tel: 6904 4922 Email: patrick.soo@a-pac.sg;collin.wong@a-pac.sg

VEHICLE DAMAGE INSPECTION REPORT

Our File No: MSIG-TPS/20-01053

17/09/2020 Date:

30896 km

REFERENCE

MSIG Insurance Handling Insurer:

Policy No: A29022516MKC (Singapore) Pte. Ltd.

Claimant Vehicle

FBM267E

Insured Vehicle

GBG6027Z

Odometer:

No: Date of Loss: 21/01/2020

No:

Nature of Claim: TP Claim No:

618204

DESCRIPTION & IDENTIFICATION OF VEHICLE

FBM267E Reg No:

Make & Model: KAWASAKI Z1000SX, 1.0 Engine No: ZRT00DE108651 Reg. Date: 14/06/2017 (Man. Year: 2017) Chassis No: JKAZRT00HJA001465

Colour: Black **Engine Capacity:** 1043 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

Footbrake (Serviceable): General Condition: Steering (Serviceable): Good Yes Yes Handbrake (Serviceable): **Engine Modification:** Pre-accident Condition: Yes Nο Average

CONDITION OF TYRES

Front Tyre Size: 120/70R17 Rear Tyre Size: 190/70R17 Rear Left Side: Front Left Side: Michelin 3 mm 4 mm Rear Right Side: Front Right Side: Michelin 0 mm 0 mm

The above values represent the remaining tyre treads depth

Repairer's	Adjuster's	Difference	Diff %
0.00	17,793.00	-17,793.00	
0.00	0.00	0.00	
0.00	630.00	-630.00	
0.00	0.00	0.00	
0.00	0.00	0.00	
ount (S\$) 0.00	18,423.00	-18,423.00	
	0.00 0.00 0.00 0.00 0.00	0.00 17,793.00 0.00 0.00 0.00 630.00 0.00 0.00 0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00 630.00 -630.00 0.00 0.00 0.00 0.00 0.00 0.00

Liable Amount (0.00%) (S\$) 0.00

INSPECTION

Date of Assignment: 24/01/2020

Revology (HQ) 31/01/2020, 01/04/2020, 25 Kaki Bukit Road 4 #01-43, #01-43 Synergy Date Inspected:

Inspected At: 10/09/2020

Singapore 417800

Estimated Period of Repair: 3.0 days

Adjuster: Manager: M. Gaddafi Patrick Soo

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

CONSISTENCY OF DAMAGES

- 1. The inspected vehicle sustained damage at the LEFT & RIGHT portion.
- 2. During visual inspection, our surveyor noted that the centre upper cowling, engine cover left, front fender, front fork left & right, shroud left and among other parts were affected.
- 3. All stated damage is subject to consistency of the accident reports.

MARKET VALUE

The market value of this vehicle was at about S\$24,000.00 at the time of the accident with PARF/COE Rebate at S\$4,508.00. The Economical Repair Limit is about S\$19,492.00. In our opinion, it is NOT economical to repair if the cost of repair exceeded \$19,492.00.

SPECIAL REMARKS

- 1. The repairer did NOT provide Repair Estimate during our pre-repair inspection.
- 2. Our surveyor recommended cost of repair is on Part by Part Basis estimated at S\$18,423.00.
- 3. The repair would require 3.0 days for completion.
- 4. This inspection was conducted on a "Without Prejudice" Basis.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 17 Sep 2020)

KAWASAKI Z1000SX 1.0 (Model not available in database) Parts: N/A

Labour: Repairer's (Price-denominated Standard List)

Print Code: A-PAC Adjusters & Surveyors Pte Ltd/FBM267E/17/09/2020 12:14

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page Validity:

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*CENTRE UPPER COWLING	Cracked / Broken	-	*- FL
2	1		*COWLING UPPER LH	Cracked	-	*- FL
3	1		*LOWER COWLING LH	Reuse	-	*- FL
4	1		*LOWER COWLING RH	Reuse	-	*- FL
5	1		*ENGINE COVER LH	Grazed / Cut	-	*-FS
6	1		*ENGINE COVER RH	Reuse	-	*- FL
7	1		*FRAME SLIDER LH	Reuse	-	*- FL
8	1		*FRONT BRAKE LEVER	Broken	-	*- FL
9	1		*FRONT BRAKE RESERVOIR	Reuse	-	*- FL
10	1		*FRONT FENDER	Grazed / Cut	-	*- FL
11	1		*FRONT HANDLEBAR	Bent / Distorted	-	*-FL
12	1		*FRONT HEADLAMP	Cracked	-	*-FL
13	1		*FRONT LH BAR END	Reuse	-	*- FL
14	1		*FRONT RH BAR END	Grazed / Cut	-	*-FL
15	1		*FRONT LH BRAKE CALIPER	Reuse	-	*- FL
16	1		*FRONT RH BRAKE CALIPER	Reuse	-	*-FL
17	1		*FRONT RH BRAKE DISC	Reuse	-	*- FL
18	1		*FRONT LH BRAKE DISC	Reuse	-	*- FL
19	1		*FRONT CLUTCH LEVER	Reuse	-	*- FL
20	1		*FRONT LH FORK	Bent	-	*- FL
21	1		*FRONT RH FORK	Bent	-	*- FL
22	1		*FRONT LH SIDE MIRROR	Reuse	-	*- FL
23	1		*FRONT RH SIDE MIRROR	Cracked	-	*- FL
24	1		*FRONT LH AXLE SLIDER	Reuse	-	*-FL
25	1		*FRONT RH AXLE SLIDER	Reuse	-	*-FL
26	1		*FRONT POLE LAMP	Reuse	-	*- FL
27	1		*FRONT RIM	Bent	-	*-FL
28	1		*FUEL TANK	Dented	-	*-FL
29	1		*FUEL TANK COVER RH	Grazed / Cut	-	*- FL
30	1		*FUEL TANK COVER LH	Reuse	-	*-FL
31 32	1		*FUEL TANK COVER CENTRE	Reuse	-	*- FL *- FL
			*METER ASSY	Reuse	-	
33 34	1		*METER COVER *EXHAUST HEADER	Cracked Reuse	-	*- FL *- FL
					-	
35 36	1		*REAR EXHAUST LH *REAR EXHAUST RH	Dented / Buckled Reuse	-	*- FL *- FL
30 37	1		*REAR LH FOOTREST	Reuse		
38	1		*REAR RH FOOTREST	Reuse	-	- r L *- F L
39	1		*REAR LH SIDE COVER	Reuse		*-FL
39 40	1		*REAR RH SIDE COVER	Reuse	-	- r L *- F L
4 0 41	1		*REAR MUDGUARD	Reuse	-	*- FL
41 42	1		*REAR TAILLAMP	Reuse	-	- F L *- F L
4 2 43	1		*SHROUD LH	Cracked / Grazed	-	*- FL
43 44	1		*SHROUD RH	Reuse	-	- r L *- F L
44	1		*SIDE STAND	Reuse	-	*- FL
45 46	1		*SIGNAL LAMP LH	Reuse	-	- r L *- F L
4 0 47			*SIGNAL LAMP RH	Reuse		*-FL
41	1		SIGNAL LAWIF KIT	Reuse	-	-FL

48	1	*REAR SWINGARM	Dented / Grazed	-	*- FL
49	1	*FORK UPPER HOLDER	Reuse	-	*- FL
50	1	*COWLING LOWER	Grazed / Cut	-	*-FL
51	1	*ESTIMATE PART PRICE		-	*19,770.00 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.					
			Sub Total (S\$)	0.00	19,770.00
- List Item Discount on L Items 0.00/10.00% (S\$)		ount on L Items 0.00/10.00% (S\$)	0.00	1,977.00	
Total Parts (S\$)		0.00	17,793.00		

A-PAC Adjusters & Surveyors Pte Ltd/FBM267E/17/09/2020 12:14. Not valid without Reference section.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Pain	twork Labour			
1	SPRAY PAINTING	New	-	0.00
<u>Lab</u>	<u>our Items</u>			
2	TO REMOVE & REFIT AFFECTED PORTION DUE TO ACCIDENT	New	-	600.00
3	TO CHECK WIRING	New	-	30.00
	Gross Labo	ur Cost (S\$)	0.00	630.00

A-PAC Adjusters & Surveyors Pte Ltd/FBM267E/17/09/2020 12:14. Not valid without Reference section.

< END OF ESTIMATES >