

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI22011359/KQY3E2**Date:** 09/05/2023**REFERENCE**

Insured/Claimant: SSL LIMOUSINE PTE LTD Policy No: DMCVSNW00138232101

Date of Loss: 07/11/2022

Nature of Claim: OD

Claim No: SNM22D208043/C01/CHNGPW

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBK7775U**

Make & Model: TOYOTA HIACE, 2.8 D DX (A)

Engine No: 1GD8613892

Reg. Date: 30/11/2020 (Man. Year: 2020)

Chassis No: GDH2012014363

Colour: Silver

Odometer: 0 km

Engine Capacity: 2754 cc

Market Value/New Car Price: S\$84,000.00

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R18

Rear Tyre Size: 245/40 R18

Front Left Side: KAPSEN 3 mm

Rear Left Side: KAPSEN 4 mm

Front Right Side: KAPSEN 3 mm

Rear Right Side: KAPSEN 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,060.00	16,835.00	8,225.00	32.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,988.80	1,048.20	2,940.60	73.72
Paintwork Labour	1,395.69	493.05	902.64	64.67
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	30,444.49	18,376.25	12,068.24	39.64
Approved Total (Overridden) (S\$)		14,700.00		
- Excess (S\$)	0.00	1,500.00	-1,500.00	
(S\$)	30,444.49	13,200.00	17,244.49	56.64
+ GST 7.00/8.00% (S\$)	2,131.11	1,056.00	1,075.11	50.45
Nett Amount (S\$)	32,575.60	14,256.00	18,319.60	56.24

INSPECTION

Date of Assignment: 14/11/2022 Present Location: Ding Auto Pte Ltd (HQ)

Ding Auto Pte Ltd (HQ)

Date Inspected: 14/11/2022 Inspected At: 176 Sin Ming Drive #04-06, Sin Ming Autocare

Singapore 575721

Estimated Period of Repair: 18.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 09 May 2023)
Parts: 213	TOYOTA HIACE 2.8 D DX (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for GBK7775U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*TOTAL PARTS		22,945.00 F	*14,720.00 F	
Supplementary #1							
2	1		*UREA TANK	Cracked	420.00 F	*420.00 F	
3	1		*UPPER A-PILLAR TRIM LH	Buckled	95.00 F	*95.00 F	
4	1		*UREA TANK CONNECTOR CPL	Cracked	1,350.00 F	*1,350.00 F	
5	1		*WIND SIDE ANGLE MIRROR LH	Missing	95.00 F	*95.00 F	
6	1		*ENGINE COMPARTMENT INSULATOR	Cracked	120.00 F	*120.00 F	
7	1		*WIPER PANEL END GARNISH LH	Mtg Distorted	35.00 F	*35.00 F	
					Total Parts (S\$)	25,060.00	16,835.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Total Paint Labour	New	1,045.80	357.00
2	Total Paint Materials	New	349.89	136.05
<u>Labour Items</u>				
3	Total Panel/Mechanical Labour	New	3,988.80	1,048.20
			Gross Labour Cost (S\$)	5,384.49
				1,541.25

Report was unsubmitted during this print-out.

< END OF ESTIMATES >