

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/EQI22011361/TNY3E2**Date:** 13/01/2023REFERENCE

Handling Insurer: EQ Insurance Company Ltd

Policy No:

**Claimant Vehicle No :** SHA7787S**Insured Vehicle No :** SJB7333P

Date of Loss: 11/11/2022

Nature of Claim: TP

Claim No: DM22HO01937

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SHA7787S**

Make &amp; Model: HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)

Engine No: G4LEKU422237

Reg. Date: 28/07/2021 (Man. Year: 2019)

Chassis No: KMH851CVLU193136

Colour: Blue

Odometer: 171779 km

Engine Capacity: 1580 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: West Lake 6 mm

Rear Left Side: West Lake 6 mm

Front Right Side: West Lake 6 mm

Rear Right Side: West Lake 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,005.08	2,005.08	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,530.00	940.00	590.00	38.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>3,535.08</b>	<b>2,945.08</b>	<b>590.00</b>	<b>16.69</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>247.46</b>	<b>206.16</b>	<b>41.30</b>	<b>16.69</b>
<b>Nett Amount (S\$)</b>	<b>3,782.54</b>	<b>3,151.24</b>	<b>631.30</b>	<b>16.69</b>

INSPECTION

Date of Assignment: 11/11/2022 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 14/11/2022 Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang)  
59 Loyang Drive  
Singapore 508969

Estimated Period of Repair: 3.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Jan 2023)
Parts:	192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA7787S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT DOOR LH	Bent	1,797.20 FL	*1,797.20 FL
2	1		*FRT FENDER LH	Bent	588.80 FL	*588.80 FL
3	1		*FRT FENDER EMBLEM BLUE- DRIVE LH	Necessary	26.60 FL	*26.60 FL
4	1		*FRT DOOR COMFORT LOGO RH	Cut	75.00 F	*75.00 F
					Sub Total (\$\$)	2,487.60 2,487.60
					- List Item Discount on L Items 20.00/20.00% (\$\$)	482.52 482.52
					Total Parts (\$\$)	2,005.08 2,005.08

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	750.00	350.00
2	SPRAY PAINTING CHARGE	New	600.00	500.00
3	TUFF KOTE	New	60.00	30.00
4	TRANSFER OF DOOR	New	120.00	60.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,530.00</b>	<b>940.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >