

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22011371/AVCE2**Date:** 02/03/2023**REFERENCE**

Insured/Claimant: LOH TECK KWANG (LUO DEGUANG)

Policy No: 7220077874

Date of Loss: 05/11/2022

Nature of Claim: OD Claim No: 9709100925SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SFM898L**

Make & Model: AUDI A5, 2.0 SPORTBACK (A)

Engine No: DEM032217

Reg. Date: 13/07/2022 (Man. Year: 2021)

Chassis No: WAUZZZF5XMA048350

Colour: Blue

Odometer: 8848 km

Engine Capacity: 1984 cc

Market Value/New Car Price: S\$245,000.00

Price:

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R18

Rear Tyre Size: 245/40 R18

Front Left Side: Hankook 6 mm

Rear Left Side: Hankook 6 mm

Front Right Side: Hankook 6 mm

Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,839.80	11,927.76	10,912.04	47.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,002.00	2,452.00	4,550.00	64.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,841.80	14,379.76	15,462.04	51.81
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	29,041.80	13,579.76	15,462.04	53.24
+ GST 8.00/8.00% (S\$)	2,323.34	1,086.38	1,236.96	53.24
Nett Amount (S\$)	31,365.14	14,666.14	16,699.00	53.24

INSPECTION

Date of Assignment: 14/11/2022

Date Inspected: 11/11/2022

Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,493.00 FS	*1,994.40 FS
2	2		*FRONT BUMPER SECURING STRIP - LH / RH	Not Necessary	79.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE - CENTER	Cracked	219.00 FS	*174.80 FS
4	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	293.00 FS	*- FS
5	1		*FRONT BUMPER AIR GUIDE - LH	Not Necessary	72.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT	Cracked	293.00 FS	*234.00 FS
7	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Not Necessary	151.00 FS	*- FS
8	1		*FRONT BUMPER OUTER GRILLE HOLE COVER - LH	Not Necessary	54.00 FS	*- FS
9	1		*FRONT BUMPER TRIM -CENTER	Not Necessary	127.00 FS	*- FS
10	1		*RADIATOR GRILLE (NPA)	Cracked	1,504.80 FS	*1,504.80 FS
11	1		*RADIATOR GRILLE COVER CAP	Damaged	141.00 FS	*112.40 FS
12	1		*RADIATOR GRILLE BRACKET	Damaged	19.00 FS	*14.64 FS
13	1		*RADIATOR SECURING PLATE	Not Necessary	12.00 FS	*- FS
14	1		*FRONT 360 CAMERA	Not Necessary	1,264.00 FS	*- FS
15	1		*FRONT BUMPER FOAM FILLER PIECE	Deformed	163.00 FS	*130.40 FS
16	1		*FRONT BUMPER REINFORCEMENT BEAM	Bent	899.00 FS	*719.20 FS
17	1		*FRONT BUMPER GUIDE SECTION - LH	Not Necessary	41.00 FS	*- FS
18	1		*FRONT BUMPER TOP COVER	Not Necessary	143.00 FS	*- FS
19	1		*CAUTION SIGN STICKER	Not Necessary	16.00 FS	*- FS
20	1		*AIR CONDITIONER STICKER	Not Necessary	9.00 FS	*- FS
21	1		*LOCK CARRIER BRACKET	Cracked	154.00 FS	*122.80 FS
22	1		*FRONT BUMPER SUPPORT - LH / RH	N/S Damaged	64.00 FS	*25.60 FS
23	2		*FRONT PARKING AID SENSOR - INNER / OUTER	Not Necessary	531.00 FS	*- FS
24	4		*FRONT PARKING AID SEAL RING	Not Necessary	10.00 FS	*- FS
25	4		*FRONT PARKING AID SEAL RING	Not Necessary	16.00 FS	*- FS
26	4		*FRONT PARKING AID SEAL RING	Not Necessary	10.00 FS	*- FS
27	1		*HORN HIGH TONE - LH	Not Necessary	134.00 FS	*- FS
28	1		*HORN BRACKET - LH	Not Necessary	33.00 FS	*- FS
29	1		*BONNET	Not Necessary	3,491.00 FS	*- FS
30	3		*BONNET IMPACT PROTECTION - CENTER / LH / RH	Damaged	93.00 FS	*24.24 FS
31	1		*BONNET STRIKER - LH	Not Necessary	56.00 FS	*- FS
32	1		*BONNET LOCK	Not Necessary	228.00 FS	*- FS
33	1		*BONNET BOWDEN CABLE - CENTER	Not Necessary	64.00 FS	*- FS
34	1		*BONNET RELEASE COVER	Not Necessary	15.00 FS	*- FS
35	1		*BONNET RELEASE CABLE COVER	Not Necessary	11.00 FS	*- FS
36	1		*BONNET BOWDEN CABLE - CENTER	Not Necessary	64.00 FS	*- FS
37	1		*HEADLIGHT - LH	Cracked	8,172.00 FS	*6,537.60 FS
38	1		*LIFT CYLINDER - LH	Not Necessary	217.00 FS	*- FS
39	1		*LIFT CYLINDER BRACKET - LH	Not Necessary	17.00 FS	*- FS
40	1		*LIFT CYLINDER CORRUGATED PIPE	Not Necessary	107.00 FS	*- FS
41	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Necessary	21.00 FS	*16.32 FS
42	1		*RADIATOR AIR GUIDE - LH / RH INNER	N/S Cracked	72.00 FS	*28.40 FS
43	2		*RADIATOR AIR GUIDE - LH / RH OUTER	Not Necessary	38.00 FS	*- FS
44	2		*RADIATOR AIR GUIDE - UPPER / LOWER	Not Necessary	44.00 FS	*- FS
45	1		*FRONT WHEEL HOUSING LINER - LH	Not Necessary	299.00 FS	*- FS
46	1		*FRONT WHEEL SPOILER - LH	Not Necessary	82.00 FS	*- FS
47	1		*FRONT NO PLATE	Cracked	150.00 FS	*80.00 FS
48	1		*SUNDRIES	Necessary	400.00 FS	*4.96 FS
49	1		*FRONT REINFORCEMENT BEAM BRACKET-LH	Bent	254.00 FS	*203.20 FS
			(Supplementary)			

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 22,839.80 11,927.76

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND LHS HEADLIGHT. TO REPAIR LHS FRONT FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,500.00	500.00
4	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER AND BONNET	New	3,000.00	550.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
6	TO DISLODGE AND REINSTALL FRONT LOCK CARRIER TO FACILITATE RENEWAL OF REINFORCEMENT BEAM BRACKET (Supplementary)	New	480.00	480.00
Gross Labour Cost (\$\$)			7,002.00	2,452.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >