

## COMFORT TRANSPORTATION PTE LTD

## REPAIR ESTIMATE

Vehicle No. : SHA5730T

Make : HYUNDAI

Model : IONIQ

Date: 10/03/22

Insurance: INCOME

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$ <del>44</del> 459.40
10	REAR BUMPER CLIPS			\$ <del>net</del> 22.00
1	REAR BUMPER CENTRE MOULDING			\$ <del>am</del> 451.25
1	REAR BUMPER REFLECTOR LAMP LH			\$ <del>x nm</del> 41.45
1	TAIL LAMP LH			\$ <del>ch</del> 935.40
1	ASSY BLIND SPOT RADAR LH			\$ <del>x nm</del> 1,625.00
1	REAR BUMPER SIDE BRACKET LH			\$ <del>kl</del> 55.80
1	REAR WHEEL HUB CAP LH			\$ <del>am</del> 346.40
			2270.25	
	SUB TOTAL			\$ 3,936.70
	LESS 20%		1816.20	\$ 787.34
	DISCOUNTED TOTAL			\$ 3,149.36
1	REAR TYRE LH			\$ <del>am</del> 216.00
1	REAR FENDER ADVERTISEMENT LOGO LH RH			\$ <del>am</del> 200.00
1	REAR FENDER PETROL STICKER			\$ <del>am</del> 15.00
			387.80	\$ 431.00
	Labour Charge			
	PANEL BEATING			\$ <del>350</del> 750.00
	SPRAY PAINTING CHARGE			\$ <del>500</del> 600.00
	CHECK ALL LIGHTING			\$ <del>30</del> 60.00
	TOTAL LABOUR		3084	\$ 1,410.00
	ESTIMATE TOTAL		4524.50	\$ 4,990.36
			2 days	

Nett 172.80

Nett

Nett

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanji 97495749  
 WP 4/00/12 E 4p  
 clb Rong after repair  
 Tanji @ the car  
 2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: