

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG122011391/TVY3Q2**Date:** 17/04/2023REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SNH1988K**Insured Vehicle No :** GBH101B

Date of Loss: 09/11/2022

Nature of Claim:

TP

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SNH1988K**

Make & Model: MERCEDES-BENZ B180, 1.6 STYLE (A)

Engine No: 27091030713215

Reg. Date: 05/08/2015 (Man. Year: 2015)

Chassis No: WDD2462422J340874

Colour: White

Odometer: 101472 km

Engine Capacity: 1595 cc

Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car PriceCONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: KAPSEN 6 mm

Rear Left Side: KAPSEN 6 mm

Front Right Side: KAPSEN 6 mm

Rear Right Side: KAPSEN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,679.70	5,858.09	8,821.61	60.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,500.00	1,650.00	850.00	34.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,179.70	7,508.09	9,671.61	56.30
Approved Total (Overridden) (S\$)		6,000.00		
Nett Amount (S\$)	17,179.70	6,000.00	11,179.70	65.08

INSPECTION

Date of Assignment: 14/11/2022

Date Inspected: 05/12/2022

Inspected At:

Win Automotive Services
60 Jalan Lam Huat #04-53
Singapore 737869

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Apr 2023)
Parts:	144	MERCEDES-BENZ B180 1.6 STYLE (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNH1988K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Deformed	1,700.00 FL	*1,404.00 FL
2	2	*REAR BUMPER SIDE RETAINER	Not Necessary	180.00 FL	*- FL
3	1	*SET REAR BUMPER FASTENERS	Necessary	20.00 FL	*20.00 FL
4	1	*REAR BUMPER REINFORCEMENT	Bent	580.00 FL	*432.00 FL
5	1	*REAR BUMPER LOWER DIFFUSER	Deformed	280.00 FL	*280.00 FL
6	1	*REAR BUMPER LOWER DIFFUSER CHROME MOULDING	Cracked	240.00 FL	*155.40 FL
7	1	*REAR BUMPER TOWING COVER	Not Necessary	95.00 FL	*- FL
8	1	*REAR BUMPER INNER CENTER FRAME	Not Necessary	298.00 FL	*- FL
9	1	*REAR BUMPER INNER SWITCH SENSOR MODULE BRACKET	Not Necessary	355.00 FL	*- FL
10	1	*BOOTLID	Bent	2,300.00 FL	*1,800.00 FL
11	1	*BOOTLID INNER LOCK	Bent	320.00 FL	*298.70 FL
12	1	*BOOTLID LOWER INNER TRIM	Not Necessary	285.00 FL	*- FL
13	1	*BOOTLID TOP INNER TRIM	Not Necessary	395.00 FL	*- FL
14	1	*BOOTLID INNER TRIM FASTERNERS	Not Necessary	30.00 FL	*- FL
15	1	*BOOTLID WEATHERSTRIP	Twisted	250.00 FL	*220.00 FL
16	1	*BOOTLID CHROME MOULDING	Cracked	290.00 FL	*290.00 FL
17	1	*BOOTLID LOGO EMBLEM	Necessary	95.00 FL	*95.00 FL
18	2	*BOOTLID LH & RH SHOCK ABSORBER	Not Necessary	450.00 FL	*- FL
19	1	*BOOTLID OUTER LOCK HANDLE ACCURATOR	Not Necessary	480.00 FL	*- FL
20	2	*BOOTLID LAMP LH & RH	Cracked	1,150.00 FL	*950.00 FL
21	1	*B180 EMBLEM	Necessary	90.00 FL	*90.00 FL
22	2	*TAILLAMP LH & RH ASSY	Not Necessary	1,250.00 FL	*- FL
23	1	*TAILLAMP LH & RH LOWER BRACKET HOLDER	Not Necessary	250.00 FL	*- FL
24	1	*REAR WINDSCREEN	Not Necessary	850.00 FL	*- FL
25	1	*REAR WINDSCREEN WIPER ASSY	Not Necessary	460.00 FL	*- FL
26	1	*REAR END PANEL	Repair	1,380.00 FL	*- FL
27	1	*REAR END PANEL TOP GARNISH	Deformed	165.00 FL	*165.00 FL
28	1	*REAR END PANEL TOP GARNISH FASTERNERS	Necessary	30.00 FL	*20.00 FL
29	2	*REAR FENDER LH & RH INNER TRIM BOARD	Not Necessary	1,180.00 FL	*- FL
30	2	*SET REAR FENDER LH & RH INNER TRIM BOARD FASTERNERS	Not Necessary	85.00 FL	*- FL
31	1	*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
32	1	*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
33	1	*REVERSE SENSOR	Not Working	200.00 FS	*200.00 FS
34	1	*REVERSE CAMERA	Not Necessary	300.00 FS	*- FS
35	1	*REAR CAR PLATE AND HOUSING	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,233.00	6,480.10
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,553.30	622.01
Total Parts (\$\$)	14,679.70	5,858.09

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT AND RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS	New	800.00	600.00
2	TO CHECK WIRING AND REWIRE	New	60.00	30.00
3	TO REMOVE AND REINSTALL REVERSE SENSOR AND REVERSE CAMERA	New	120.00	50.00
4	TO ANTI-RUST	New	120.00	30.00
5	TO REMOVE AND REINSTALL BOOTLID COMPONENTS	New	100.00	60.00
6	TO PUTTY AND SPRAY PAINT OF AFFECTED AREAS	New	800.00	700.00
7	TO CLEAR /RESET FAULT CODE	New	250.00	0.00
8	TO REMOVE AND REINSTALL REAR BOOT UPHOLSTERY	New	100.00	60.00
9	TO REMOVE AND REINSTALL REAR WINDSCREEN CONDUCT WATER TEST LEAK	New	150.00	120.00
Gross Labour Cost (S\$)			2,500.00	1,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >