

ASS. REC BY: Taufik

REF: CS/EG/22011391/Try3

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / VS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: GBH 101B
 Policy No _____
 Claims No CDMCG22002416
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SNH1988K Yr Regn: 2015 Aug
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Mercedes Benz B180 C.C. 1590
 Colour white A/C: Insured / Std / NI / NA
 Sp. Reading 10472 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: W1D2462422J340874
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brakes: In order / Jammed / Leaked / Burnt or _____
 Modl: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 205/55R16
 R: 11
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Kapsen
 Front R/Bal. 6 mm Rear R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 9/11/2022 D.O.I. 5/12/22
 Survey held at Win Auto
 Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or _____
 The U/C / Chassis frame / Body Structure affected due to collision.

N/S	O/S

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$55K
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS WP
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time	Action / Instruction
12/4/23	Taufikh confirmed LS \$6000 (Red 11,179.70, 65%)

Date/Time, File Pass to? ☐ : Preli. Report
☐ : Final Report

1) _____
 Date/Time, File Return to?
 2) 13/4/23-typist

Rep. / Former: Merimen
 Lump Sum / L.B.: \$6000

Days Of Repair: 6
 Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee: _____
 Transportation: _____
 S + RS: _____
 Photos _____
 Others _____
 TOTAL _____

WIN AUTOMOTIVE SERVICES
SNH 1988K MERCEDES B180

Estimate - Parts(s)

S/N Qty Descriptions

Amount

LIST ITEMS:-

1	1	rear bumper
2	2	rear bumper side retainer
3	1set	rear bumper fasteners
4	1	rear bumper reinforcement
5	1	rear bumper lower diffuser
6	1	rear bumper lower diffuser chrome moulding
7	1	rear bumper towing cover
8	1	rear bumper inner center frame
10	1	rear bumper inner switch sensor module bracket
11	1	bootlid
12	1	bootlid inner lock
13	1	bootlid lower inner trim
	1	bootlid top inner trim
14	1	bootlid inner trim fasteners
15	1	bootlid weatherstrip
16	1	bootlid chrome moulding
17	1	bootlid logo emblem
18	2	bootlid LH & RH shock absorber
19	1	bootlid outer lock handle accurator
20	2	bootlid lamp LH & RH
21	1	B180 emblem
22	2	taillamp LH & RH assy
23	1	taillamp LH & RH lower bracket holder
24	1	rear windscreen
25	1	rear windscreen wiper assy
26	1	rear end panel
27	1	rear end panel top garnish
28	1	rear end panel top garnish fasteners
29	2	rear fender LH & RH inner trim board
30	2set	rear fender LH & RH inner trim board fasteners

1700	de ✓
180	?
20	ner ✓
580	?
280	?
240	ner ✓
95	x
298	?
355	x
2300	bt ✓
320	?
285	?
395	x
30	?
250	?
290	ner ✓
95	ner ✓
450	x
480	x
1150	?
90	ner ✓
1250	x ?
250	x
850	x
460	x
1380	Ry
165	?
30	?
1180	x
85	x

15533

1553.3

13979.7

Less 10%

Special Nett Item

1	rear end panel sealant
2	rear windscreen sealant
3	reverse sensor

80	40 ?
80	60 ner ✓
200	ner ✓

- 4 reverse camera
5 rear car plate and housing

300 200?
40

TOTAL

700

Estimate - Labour(s)

S/N	Qty	Descriptions	Amount
		B/F	
		LABOUR & OTHER CHARGES:-	
1		To panel beat and renewal of all necessary damaged body parts	800 600
2		To check wiring and rewire	60 30
4		to remove and reinstall reverse sensor and reverse camera	120 50.
5		To anti-rust	120 30
6		to remove and reinstall bootlid components	100 60
7		To putty and spray-paint of affected areas	800 700
8		To clear/reset fault code	250 150?
9		to remove and reinstall rear boot upholstery	100 60
11		to remove and reinstall rear windscreen conduct water test leak	150 120
			2500

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanfmin 97415749
Wrt 05/17/22 @ 440pm
L/s Repair of the repair
06 days
Tanfmin @ Consultants-wm