

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22011392/UYA3Q2**Date:** 17/04/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800083171		
Claimant Vehicle No :	SLH1026K	Insured Vehicle No :	SLD2333M		
Date of Loss:	10/11/2022	Nature of Claim:	TP	Claim No:	9940360711SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLH1026K	Engine No:	L15B4405532
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Chassis No:	RU11205532
Reg. Date:	24/10/2016 (Man. Year: 2016)	Odometer:	138317 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,843.44	1,396.48	446.96	24.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,030.00	1,000.00	1,030.00	50.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,873.44	2,396.48	1,476.96	38.13
Approved Total (Overridden) (S\$)		1,650.00		
(S\$)	3,873.44	1,650.00	2,223.44	57.40
+ GST 7.00/7.00% (S\$)	271.14	115.50	155.64	57.40
Nett Amount (S\$)	4,144.58	1,765.50	2,379.08	57.40
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,067.50		

INSPECTION

Date of Assignment:	20/12/2022	Hock Wah Motor Workshop Pte Ltd (Bedok)
Date Inspected:	20/12/2022 Inspected At:	Blk 3011, Bedok Industrial Park E., #01-2008/2010/2012
Estimated Period of Repair:	3.0 days	Singapore 489977

Adjuster: MARCUS CHUA**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Badly Dented	1,193.10 FL	*997.00 FL
2	1		*TAILGATE EMBLEM	Not Necessary	19.30 FL	*- FL
3	1		*TAILGATE LOGO -VEZEL	Necessary	43.30 FL	*43.30 FL
4	1		*TAILGATE INNER LOCK	Not Necessary	96.60 FL	*- FL
5	1		*REAR BUMPER	Dented	405.30 FL	*405.30 FL
6	1		*SET REVERSE SENSOR	Shorted	329.36 FS	*200.00 FS
7	2		*REAR WINDSCREEN SEALANT	Necessary	48.00 FS	*40.00 FS
8	1		*REAR NUMBER PLATE	Not Necessary	30.00 FS	*- FS
9	1		*REAR NUMBER PLATE	Not Necessary	30.00 FS	*- FS
10	1		*END PANEL (NPA)	Repair	0.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,194.96	1,685.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	351.52	289.12
Total Parts (\$\$)	1,843.44	1,396.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	800.00	400.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	800.00	400.00
3	ANTI RUST COATING	New	100.00	30.00
4	TO REMOVE & REFIT WINDSCREEN	New	180.00	120.00
5	TO REMOVE & REFIT REVERSE SENSOR	New	150.00	50.00
Gross Labour Cost (\$\$)			2,030.00	1,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >