

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22011394/UYA3Q2**Date:** 17/04/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100496627
Claimant Vehicle No :	SJT9289B	Insured Vehicle No :	SLL1811P
Date of Loss:	12/11/2022	Nature of Claim:	TP
		Claim No:	5053835435SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJT9289B	Engine No:	3ZRA396840
Make & Model:	TOYOTA WISH, 2.0 (A)	Chassis No:	JTDGJ20W205001181
Reg. Date:	10/11/2009 (Man. Year: 2009)	Odometer:	193684 km
Colour:	White		
Engine Capacity:	1987 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,253.00	12,077.07	10,175.93	45.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,410.00	4,260.00	1,150.00	21.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	27,663.00	16,337.07	11,325.93	40.94
Approved Total (Overridden) (S\$)		13,000.00		
Nett Amount (S\$)	27,663.00	13,000.00	14,663.00	53.01
+ Loss of Use (20.0 x S\$80.00/day) (S\$)		1,600.00		
Nett Liability (S\$)		14,600.00		

INSPECTION

Date of Assignment:	14/11/2022	Nineteen Autowerks Pte Ltd (HQ) BLK 15 KAKI BUKIT ROAD 4 #01-53 BARTLEY BIZ CENTRE Singapore 417808
Date Inspected:	14/11/2022 Inspected At:	
Estimated Period of Repair:	20.0 days	

Adjuster: MARCUS CHUA**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Badly Dented	1,603.20 FL	*1,485.10 FL
2	1		*TAILGATE OUTER CHROME GARNISH	Not Necessary	365.10 FL	*- FL
3	1		*TAILGATE LOGO	Necessary	106.50 FL	*86.50 FL
4	1		*TAILGATE WINDSCREEN MOULDING	Necessary	185.30 FL	*185.30 FL
5	1		*REAR WIPER MOTOR	Not Necessary	399.60 FL	*- FL
6	1		*REAR WIPER ARM	Not Necessary	89.40 FL	*- FL
7	1		*REAR WIPER COVER	Not Necessary	72.00 FL	*- FL
8	1		*TAILGATE INNER LOCK	Dented / Jammed	309.10 FL	*309.10 FL
9	1		*TAILGATE LOCK STRIKER	Not Necessary	92.10 FL	*- FL
10	1		*TAILGATE INNER TRIM BOARD	Deformed / Torn	585.60 FL	*481.20 FL
11	2		*TAILGATE HYDRAULIC DAMPER	Not Necessary	444.20 FL	*- FL
12	2		*TAILGATE LAMPS	Not Necessary	778.00 FL	*- FL
13	2		*REAR NUMBER PLATE LAMP	Not Necessary	196.40 FL	*- FL
14	1		*REAR BUMPER	Distorted	1,016.40 FL	*655.10 FL
15	2		*REAR BUMPER SIDE RETAINER	Bent	197.20 FL	*197.20 FL
16	1		*REAR BUMPER REINFORCEMENT	No such part	428.00 FL	*- FL
17	1		*REAR BUMPER DAMPER	N/S Bent	174.20 FL	*87.10 FL
18	2		*REAR BUMPER REFLECTOR	Not Necessary	303.00 FL	*- FL
19	1		*REAR DIFFUSER	No such part	652.50 FL	*- FL
20	1		*REAR END PANEL (LOWER)	Badly Dented	350.00 FL	*350.00 FL
21	1		*REAR END PANEL (OUTER)	Badly Dented	519.80 FL	*519.80 FL
22	1		*REAR END PANEL TOP GARNISH	Twisted	369.00 FL	*322.10 FL
23	1		*TAILLAMPS	N/S Cracked	1,184.00 FL	*592.00 FL
24	2		*TAILLAMPS LOWER BRACKET	Not Necessary	187.60 FL	*- FL
25	2		*REAR FENDERS	Repair	1,407.20 FL	*- FL
26	2		*REAR FENDERS INNER TRIM BOARD	Deformed / Torn	772.00 FL	*772.00 FL
27	1		*EXHAUST PIPE ASSY	Not Necessary	910.20 FL	*- FL
28	3		*EXHAUST MOUNTING	Not Necessary	150.90 FL	*- FL
29	1		*REAR FLOOR PANEL	Crumpled / Buckled	1,880.80 FL	*1,145.80 FL
30	1		*REAR FLOOR PANEL TOP BOARD	Dented / Warped	425.00 FL	*425.00 FL
31	1		*FRONT BONNET	Dented / Buckled	1,256.00 FL	*845.10 FL
32	2		*BONNET HINGES	Not Necessary	178.80 FL	*- FL
33	1		*BONNET INNER LOCK	Bent	214.70 FL	*166.50 FL
34	1		*BONNET LOGO	Necessary	110.10 FL	*86.50 FL
35	1		*FRONT GRILLE	Cracked	321.00 FL	*321.00 FL
36	1		*FRONT BUMPER	Dented	786.50 FL	*725.10 FL
37	2		*FRONT BUMPER SIDE RETAINER	Bent	208.00 FL	*208.00 FL
38	1		*FRONT BUMPER CENTRE GRILLE	Torn	186.00 FL	*186.00 FL
39	1		*FRONT BUMPER INNER SPONGE	Torn	108.00 FL	*108.00 FL
40	1		*FRONT BUMPER REINFORCEMENT	Dented	485.00 FL	*392.20 FL
41	2		*FRONT FOGLAMP COVERS	Twisted	221.80 FL	*221.80 FL
42	1		*FRONT SUPPORT PANEL	Bent	956.00 FL	*855.10 FL
43	1		*FRONT BUMPER UNDER COVER	Torn	327.50 FL	*288.50 FL
44	2		*HEADLAMPS	Cracked	1,303.00 FL	*1,303.00 FL
45	2		*FRONT FOG LAMPS	Cracked	756.00 FL	*756.00 FL
46	1		*CONDENSER	Bent / Punctured	680.00 FL	*680.00 FL
47	2		*FAN BLADE	Not Necessary	394.00 FL	*- FL
48	1		*FAN COWLING	Not Necessary	256.00 FL	*- FL
49	1		*FAN MOTOR	Not Necessary	275.30 FL	*- FL
50	1		*FRONT BUMPER SPOILER	Torn	1,406.00 FL	*680.00 FL
51	1		*SUNDRIES	Not Necessary	60.00 FS	*- FS
52	1		*SET TAILGATE OUTER GARNISH CLIPS	Not Necessary	40.00 FS	*- FS
53	1		*SET TAILGATE TRIMBOARD CLIPS	Necessary	50.00 FS	*30.00 FS
54	1		*SET TAILGATE INNER GARNISH SIDE & TOP CLIPS	Not Necessary	105.00 FS	*- FS
55	1		*TAILGATE WINDSCREEN PRIMER & CLEANER	Not Necessary	100.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	80.00 FS	*40.00 FS
57	1		*TAILGATE WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS
58	1		*TAILGATE SEALANT	Not Necessary	220.00 FS	*- FS
59	1		*REAR NUMBER PLATE	Not Necessary	60.00 FS	*- FS
60	1		*FRONT NUMBER PLATE	Bent	60.00 FS	*40.00 FS
61	1		*REAR WIPER BLADE	Not Necessary	80.00 FS	*- FS
62	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	40.00 FS	*- FS
63	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*50.00 FS
64	1		*SET FRONT BUMPER CLIPS	Necessary	100.00 FS	*50.00 FS
65	1		*SET FRONT GRILLE CLIPS	Not Necessary	40.00 FS	*- FS
66	1		*SET FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
67	4		*SET RADIATOR HOSE CLIPS	Not Necessary	60.00 FS	*- FS
68	1		*RADIATOR COOLANT	Not Necessary	100.00 FS	*- FS
69	1		*REVERSE CAMERA	Not Necessary	420.00 FS	*- FS
70	1		*SET REAR BUMPER CLIPS	Necessary	100.00 FS	*50.00 FS
71	1		*SET REAR REVERSE SENSOR	Shorted	350.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	28,899.00	15,936.10
- List Item Discount on L Items 25.00/25.00% (S\$)	6,646.00	3,859.03
Total Parts (S\$)	22,253.00	12,077.07

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	2,000.00	1,900.00
2	SPRAY PAINTING	New	1,800.00	1,800.00
3	TO REMOVE & REFIT REAR REVERSE SENSOR	New	150.00	50.00
4	TO REMOVE & REFIT INTERIOR UPHOLSTERY	New	200.00	80.00
5	TO REMOVE & REFIT TAILGATE COMPONENT	New	100.00	60.00
6	TO REMOVE & REFIT TAILGATE WINDSCREEN	New	180.00	120.00
7	TO REMOVE & REFIT EXHAUST PIPE ASSY	New	200.00	0.00
8	TO REMOVE & REFIT RADIATOR	New	250.00	0.00
9	TO REMOVE & REFIT CONDENSER & REFILL AIR CON GAS	New	250.00	100.00
10	CHECK WIRING SYSTEM AFTER DISCONNECT & CONNECT	New	80.00	30.00
11	TO APPLY UNDERCOATING FOR RUST ROOFING	New	200.00	120.00
Gross Labour Cost (S\$)			5,410.00	4,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >