

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22011396/TVY3Q2**Date:** 16/05/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00154782100

Claimant Vehicle No : FBT4528P **Insured Vehicle No :** YQ8182U

Date of Loss: 22/10/2022 Nature of Claim: TP Claim No: SNM22D207644/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBT4528P**

Make & Model: YAMAHA AEROX 155A, 155cc Engine No: G3P4E0026572

Reg. Date: 26/02/2022 (Man. Year: 2021) Chassis No: MH3SG6420MJ015131

Colour: Silver Odometer: 0 km

Engine Capacity: 155 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 110/80 R14 Rear Tyre Size: 170/70 R14

Front Left Side: Maxxis 5 mm Rear Left Side: Maxxis 5 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,244.22	5,459.22	7,785.00	58.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,250.00	650.00	600.00	48.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,494.22	6,109.22	8,385.00	57.85
Approved Total (Overridden) (S\$)		4,900.00		
(S\$)	14,494.22	4,900.00	9,594.22	66.19
+ GST 8.00/8.00% (S\$)	1,159.54	392.00	767.54	66.19
Nett Amount (S\$)	15,653.76	5,292.00	10,361.76	66.19

INSPECTION

Date of Assignment: 14/11/2022

Date Inspected: 14/11/2022 Inspected At: Erzat Lee Motor Trading Pte Ltd (HQ)
Synergy@KB 25, Kaki Bukit Road 4 #03-37
Singapore 417800

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 15 May 2023)	
Parts:	N/A	YAMAHA AEROX 155A 155cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBT4528P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SET FORK	Bent	550.00 FL	*450.00 FL
2	1		*FORK -UNDER BRACKET	Bent	200.00 FL	*120.00 FL
3	1		*STEERING CONE	Necessary	200.00 FL	*100.00 FL
4	1		*FRONT SPORT RIM	Dented	480.00 FL	*300.00 FL
5	1		*FRONT TYRES	Not Necessary	150.00 FL	*- FL
6	1		*FRONT TYRES SHAFT	Bent	120.00 FL	*60.00 FL
7	1		*FRONT DISC BRAKE	Bent	180.00 FL	*120.00 FL
8	1		*FRONT CALIPER	Dented	280.00 FL	*180.00 FL
9	1		*FRONT ABS PLATE	Not Necessary	100.00 FL	*- FL
10	1		*FRONT FENDER INNER COVER	Cracked	180.00 FL	*180.00 FL
11	1		*SET CAMERA	Distorted	350.00 FL	*200.00 FL
12	1		*SET HEAD LIGHT	Cracked	500.00 FL	*380.00 FL
13	1		*HEAD LAMP ASSY	Bent	280.00 FL	*180.00 FL
14	1		*ABS PUMP	Not Necessary	1,200.00 FL	*- FL
15	1		*FRONT SIGNAL LIGHT RIGHT	Cracked	180.00 FL	*100.00 FL
16	1		*FRONT SIGNAL LEFT	Not Necessary	180.00 FL	*- FL
17	1		*BODY UNDER COVER	Deformed	250.00 FL	*180.00 FL
18	1		*SET IGNITION KEY	Cracked	700.00 FL	*350.00 FL
19	1		*ECU	Not Necessary	800.00 FL	*- FL
20	1		*PANEL COVER	Cracked	180.00 FL	*120.00 FL
21	1		*PANEL INNER COVER	Distorted	280.00 FL	*160.00 FL
22	1		*HEAD LIGHT PANEL COVER	Cracked	120.00 FL	*120.00 FL
23	1		*INNER BOX COVER	Not Necessary	200.00 FL	*- FL
24	1		*FRONT FAIRING INNER COVER RIGHT	Distorted	150.00 FL	*150.00 FL
25	1		*FRONT FAIRING INNER COVER LEFT	Not Necessary	150.00 FL	*- FL
26	1		*ALARM SWITCH SENSOR	Not Necessary	100.00 FL	*- FL
27	1		*HANDLE BAR	Bent	220.00 FL	*130.00 FL
28	1		*SET MIRROR	Cracked	120.00 FL	*80.00 FL
29	1		*BRAKE LEVER RIGHT	Not Necessary	80.00 FL	*- FL
30	1		*BRAKE LEVER LEFT	Bent	80.00 FL	*40.00 FL
31	1		*MIRROR BRACKET	Not Necessary	100.00 FL	*- FL
32	1		*HANDLE BAR END	Cut	120.00 FL	*60.00 FL
33	1		*HANDLE COVER 1	Not Necessary	150.00 FL	*- FL
34	1		*HANDLE COVER 2	Not Necessary	100.00 FL	*- FL
35	1		*IU UNIT	Cut	155.80 FL	*155.80 FL
36	1		*IU BRACKET	Not Necessary	50.00 FL	*- FL
37	1		*SET WIRE HARNESS	Not Necessary	900.00 FL	*- FL
38	1		*FRONT NUMBER PLATE	Missing	30.00 FL	*30.00 FL
39	1		*FRONT FOOTREST BOARD RIGHT	Deformed	250.00 FL	*200.00 FL
40	1		*FRONT FOOTREST BOARD LEFT	Deformed	250.00 FL	*200.00 FL
41	1		*FRONT FOOTREST UNDER COVER RIGHT	Distorted	180.00 FL	*140.00 FL
42	1		*FRONT FOOTREST UNDER COVER LEFT	Distorted	180.00 FL	*140.00 FL
43	1		*MAINSTAND	Bent	400.00 FL	*180.00 FL
44	1		*AIR BOX COVER	Cut	180.00 FL	*180.00 FL
45	1		*CVT HOUSING COVER	Not Necessary	200.00 FL	*- FL
46	1		*SIDE COVER INNER LEFT	Not Necessary	150.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*SIDE COVER INNER RIGHT	Not Necessary	150.00 FL	*- FL
48	1		*REAR FENDER REFLECTOR	Not Necessary	120.00 FL	*- FL
49	1		*REAR BOX	Cut	500.00 FL	*350.00 FL
50	1		*RADIATOR PANEL COVER	Cut	200.00 FL	*150.00 FL
51	1		*EXHAUST COVER	Cut	180.00 FL	*120.00 FL
52	1		*REAR SWING ARM	Not Necessary	380.00 FL	*- FL
53	1		*COVERSET SILVER /MATTE	Cracked	800.00 FL	*400.00 FL
54	1		*REAR FOOTREST RIGHT	Not Necessary	150.00 FL	*- FL
55	1		*ABS CABLE WIRE HANDLE GRIP	Not Necessary	200.00 FL	*- FL
56	1		*HANDLE GRIP	Cut	80.00 FL	*60.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	14,715.80	6,065.80
- List Item Discount on L Items 10.00/10.00% (\$)	1,471.58	606.58
Total Parts (\$)	13,244.22	5,459.22

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR	New	800.00	450.00
2	PRESS BODY	New	450.00	200.00
			Gross Labour Cost (S\$)	650.00
			1,250.00	650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >