

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)  
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
 Singapore 408933  
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/MSG22011404/UWY3E2  
**Date:** 01/12/2022

### REFERENCE

|                              |                                      |                             |             |
|------------------------------|--------------------------------------|-----------------------------|-------------|
| Handling Insurer:            | MSIG Insurance (Singapore) Pte. Ltd. | Policy No:                  | 30001960519 |
| <b>Claimant Vehicle No :</b> | SNA2643K                             | <b>Insured Vehicle No :</b> | SLL9020C    |
| Date of Loss:                | 13/11/2022                           | Nature of Claim:            | TP          |
|                              |                                      | Claim No:                   | 290847      |

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SNA2643K</b>                   | Engine No:  | 27492030758505    |
| Make & Model:               | MERCEDES-BENZ E200, 2.0 AVG (A)   | Chassis No: | WDD2130422A072623 |
| Reg. Date:                  | 14/10/2018 (Man. Year: 2016)      | Odometer:   | 60946 km          |
| Colour:                     | Green                             |             |                   |
| Engine Capacity:            | 1991 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |              |                  |              |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size:  | 245/35Z R20  | Rear Tyre Size:  | 275/30Z R20  |
| Front Left Side:  | Pirelli 6 mm | Rear Left Side:  | Pirelli 6 mm |
| Front Right Side: | Pirelli 6 mm | Rear Right Side: | Pirelli 6 mm |

*The above values represent the remaining tyre treads depth*

| COST OF CLAIMS                           | Repairer's       | Adjuster's      | Difference      | Diff %       |
|--|------------------|-----------------|-----------------|--------------|
| Parts                                    | 8,209.04         | 1,736.60        | 6,472.44        | 78.85        |
| Miscellaneous Items                      | 0.00             | 0.00            | 0.00            |              |
| Labour                                   | 2,550.00         | 770.00          | 1,780.00        | 69.80        |
| Paintwork Labour                         | 0.00             | 0.00            | 0.00            |              |
| Towing                                   | 0.00             | 0.00            | 0.00            |              |
| <b>Calculated Gross Total (S\$)</b>      | <b>10,759.04</b> | <b>2,506.60</b> | <b>8,252.44</b> | <b>76.70</b> |
| <b>Approved Total (Overridden) (S\$)</b> |                  | <b>2,000.00</b> |                 |              |
| <b>Nett Amount (S\$)</b>                 | <b>10,759.04</b> | <b>2,000.00</b> | <b>8,759.04</b> | <b>81.41</b> |

### INSPECTION

|                             |            |  |
|-----------------------------|------------|--|
| Date of Assignment:         | 15/11/2022 |  |
| Date Inspected:             | 15/11/2022 | Inspected At: Nineteen Autowerks Pte Ltd - Woodlands (HQ)<br>39 Woodlands Close, MEGA@Woodlands #01-24<br>Singapore 737856 |
| Estimated Period of Repair: | 3.0 days   |  |

**Adjuster:** MARCUS CHUA

**Manager:** XinYu

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|  |  |
|--|--|
| <b>Part Source:</b> MRM-SG                                   | Version: 1.0 (Last Synchronised: 21 Nov 2022)  |
| <b>Parts:</b> 143  | MERCEDES-BENZ E200 2.0 AVG (A) (Catalogue:Merimen Singapore 1.0)   |
| <b>Labour:</b> Repairer's                                    | (Price-denominated Standard List)  |
| <b>Print Code:</b> (Unsubmitted, no print-code for SNA2643K) |  |
| <b>Validity:</b>   | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| <b>Further Info:</b>   | Items/values not in reference catalogue are prefixed with an asterisk *.   |

### Recommended Parts

| No. | Qty | Part No. | Particulars                          | Condition     | Repairer's  | Amount       |
|-----|-----|----------|--------------------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *REAR BUMPER                         | Dented / Torn | 2,225.60 FL | *1,874.00 FL |
| 2   | 2   |          | *REAR BUMPER BRACKET                 | Not Necessary | 268.00 FL   | *- FL        |
| 3   | 2   |          | *REAR BUMPER SIDE RETAINER           | Not Necessary | 296.00 FL   | *- FL        |
| 4   | 1   |          | *REAR BUMPER CARRIER                 | Not Necessary | 132.00 FL   | *- FL        |
| 5   | 2   |          | *REAR BUMPER TOW COVER (RH)          | Not Necessary | 300.00 FL   | *- FL        |
| 6   | 1   |          | *REAR BUMPER LOWER LIP               | Repair        | 655.00 FL   | *- FL        |
| 7   | 1   |          | *REAR BUMPER EXHAUST COVER (RH)      | Not Necessary | 495.00 FL   | *- FL        |
| 8   | 1   |          | *REAR BUMPER LOWER GUIDE             | Not Necessary | 283.00 FL   | *- FL        |
| 9   | 1   |          | *REAR BUMPER SIDE REFLECTOR (RH)     | Not Necessary | 170.00 FL   | *- FL        |
| 10  | 1   |          | *REAR BUMPER REINFORCEMENT W BRACKET | Not Necessary | 930.00 FL   | *- FL        |
| 11  | 1   |          | *REAR EXHAUST PIPE                   | Not Necessary | 1,545.00 FL | *- FL        |
| 12  | 1   |          | *REAR EXHAUST PIPE MOUNTING          | Not Necessary | 108.00 FL   | *- FL        |
| 13  | 1   |          | *REAR UNDERCOVER (RH)                | Not Necessary | 458.00 FL   | *- FL        |
| 14  | 1   |          | *SUNDRIES                            | Not Necessary | 60.00 FS    | *- FS        |
| 15  | 1   |          | *SET REAR BUMPER CLIPS               | Necessary     | 70.00 FS    | *50.00 FS    |
| 16  | 1   |          | *SET REAR BUMPER RIVETS              | Not Necessary | 100.00 FS   | *- FS        |
| 17  | 4   |          | *REAR REVERSE SENSORS                | Serviceable   | 900.00 FS   | *- FS        |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|  |                 |                 |
|--|-----------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>8,995.60</b> | <b>1,924.00</b> |
| <b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b> | 786.56          | 187.40          |
| <b>Total Parts (\$\$)</b>                                  | <b>8,209.04</b> | <b>1,736.60</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                  | Particulars                                    | Lab.Type | Repairer's                      | Amount          |
|---------------------|--|----------|---------------------------------|-----------------|
| <b>Labour Items</b> |  |          |                                 |                 |
| 1                   | PANEL BEATING                                  | New      | 1,200.00                        | 320.00          |
| 2                   | SPRAY PAINTING                                 | New      | 800.00                          | 400.00          |
| 3                   | TO REMOVE & REFIT EXHAUST PIPE                 | New      | 200.00                          | 0.00            |
| 4                   | TO REMOVE & REFIT REVERSE SENSORS              | New      | 150.00                          | 50.00           |
| 5                   | CHECK WIRING SYSTEM AFTER DISCONNECT & CONNECT | New      | 100.00                          | 0.00            |
| 6                   | TO APPLY UNDERCOATING FOR RUST ROOFING         | New      | 100.00                          | 0.00            |
|                     |  |          | <b>Gross Labour Cost (\$\$)</b> | <b>2,550.00</b> |
|                     |  |          |                                 | <b>770.00</b>   |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >