

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22011404/UWY3E2**Date:** 21/11/2022REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 30001960519

Claimant Vehicle No : SNA2643K**Insured Vehicle No :** SLL9020C

Date of Loss: 13/11/2022

Nature of Claim: TP Claim No: 290847

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SNA2643K**

Make & Model: MERCEDES-BENZ E200, 2.0 AVG (A)

Engine No: 27492030758505

Reg. Date: 14/10/2018 (Man. Year: 2016)

Chassis No: WDD2130422A072623

Colour: Green

Odometer: 60946 km

Engine Capacity: 1991 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/35Z R20

Rear Tyre Size: 275/30Z R20

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,209.04	1,736.60	6,472.44	78.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,550.00	770.00	1,780.00	69.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,759.04	2,506.60	8,252.44	76.70
Approved Total (Overridden) (S\$)		2,000.00		
Nett Amount (S\$)	10,759.04	2,000.00	8,759.04	81.41

INSPECTION

Date of Assignment: 15/11/2022

Date Inspected: 15/11/2022 Inspected At:

Nineteen Autowerks Pte Ltd - Woodlands (HQ)
39 Woodlands Close, MEGA@Woodlands #01-24
Singapore 737856

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(FOR MANDATE ONLY)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Nov 2022)
Parts:	143	MERCEDES-BENZ E200 2.0 AVG (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNA2643K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Torn	2,225.60 FL	*1,874.00 FL
2	2		*REAR BUMPER BRACKET	Not Necessary	268.00 FL	*- FL
3	2		*REAR BUMPER SIDE RETAINER	Not Necessary	296.00 FL	*- FL
4	1		*REAR BUMPER CARRIER	Not Necessary	132.00 FL	*- FL
5	2		*REAR BUMPER TOW COVER (RH)	Not Necessary	300.00 FL	*- FL
6	1		*REAR BUMPER LOWER LIP	Repair	655.00 FL	*- FL
7	1		*REAR BUMPER EXHAUST COVER (RH)	Not Necessary	495.00 FL	*- FL
8	1		*REAR BUMPER LOWER GUIDE	Not Necessary	283.00 FL	*- FL
9	1		*REAR BUMPER SIDE REFLECTOR (RH)	Not Necessary	170.00 FL	*- FL
10	1		*REAR BUMPER REINFORCEMENT W BRACKET	Not Necessary	930.00 FL	*- FL
11	1		*REAR EXHAUST PIPE	Not Necessary	1,545.00 FL	*- FL
12	1		*REAR EXHAUST PIPE MOUNTING	Not Necessary	108.00 FL	*- FL
13	1		*REAR UNDERCOVER (RH)	Not Necessary	458.00 FL	*- FL
14	1		*SUNDRIES	Not Necessary	60.00 FS	*- FS
15	1		*SET REAR BUMPER CLIPS	Necessary	70.00 FS	*50.00 FS
16	1		*SET REAR BUMPER RIVETS	Not Necessary	100.00 FS	*- FS
17	4		*REAR REVERSE SENSORS	Serviceable	900.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,995.60	1,924.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	786.56	187.40
Total Parts (\$\$)	8,209.04	1,736.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,200.00	320.00
2	SPRAY PAINTING	New	800.00	400.00
3	TO REMOVE & REFIT EXHAUST PIPE	New	200.00	0.00
4	TO REMOVE & REFIT REVERSE SENSORS	New	150.00	50.00
5	CHECK WIRING SYSTEM AFTER DISCONNECT & CONNECT	New	100.00	0.00
6	TO APPLY UNDERCOATING FOR RUST ROOFING	New	100.00	0.00
Gross Labour Cost (\$\$)			2,550.00	770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >