

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EGI22011405/RVY3E2**Date:** 22/12/2022REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : XB9639D**Insured Vehicle No :** YP3644S

Date of Loss: 10/11/2022

Nature of Claim: TP

Claim No: CDMCG22002419

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **XB9639D**

Make & Model: ISUZU FVR34SUQDC, 7.8 D (M)

Engine No: 6D24350901

Reg. Date: 06/06/2005 (Man. Year: 2004)

Chassis No: FV517JA00581

Colour: White

Odometer: 444108 km

Engine Capacity: 11945 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5

Rear Tyre Size:

295/80 R22.5 (D)

Front Left Side: Unirun 8 mm

Rear Left Side:

Unirun 8/8 mm

Front Right Side: Unirun 8 mm

Rear Right Side:

Unirun 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,796.50	6,246.25	1,550.25	19.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,180.00	1,910.00	1,270.00	39.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,976.50	8,156.25	2,820.25	25.69
Approved Total (Overridden) (S\$)		6,500.00		
(S\$)	10,976.50	6,500.00	4,476.50	40.78
+ GST 7.00/7.00% (S\$)	768.36	455.00	313.36	40.78
Nett Amount (S\$)	11,744.86	6,955.00	4,789.86	40.78

INSPECTION

Date of Assignment: 21/11/2022

Date Inspected: 21/11/2022 Inspected At:

Wah Hong Motors & Credit Pte Ltd (HQ)

38 Toh Guan Road East, #01-57, Enterprise Hub
Singapore 608581

Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 15 Dec 2022)	
Parts:	N/A	ISUZU FVR34SUQDC 7.8 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XB9639D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT CORNER TOP GARNISH LH	Cracked	1,044.00 FL	*1,044.00 FL
2	1		*HEADLAMP LH	Not Necessary	514.00 FL	*- FL
3	1		*SIGNAL LAMP LH	Cracked	158.00 FL	*158.00 FL
4	1		*SIGNAL LAMP GARNISH LH	Cracked	318.00 FL	*318.00 FL
5	1		*CENTER GRILLE OUTER GARNISH	Cracked	681.00 FL	*681.00 FL
6	1		*FRONT BUMPER	Bent	960.00 FL	*960.00 FL
7	1		*FRONT BUMPER INNER BRACKET	Not Necessary	400.00 FL	*- FL
8	1		*FOG LAMP LH	Not Necessary	285.00 FL	*- FL
9	1		*FOG LAMP GARNISH LH	Cracked	110.00 FL	*110.00 FL
10	1		*FRONT DOOR LH	Torn	3,200.00 FL	*3,200.00 FL
11	1		*FRONT DOOR UPPER HINGE LH	Not Necessary	189.00 FL	*- FL
12	1		*FRONT DOOR LOWER HINGE LH	Not Necessary	189.00 FL	*- FL
13	1		*FRONT DOOR SIGNAL LAMP LH	Cracked	78.00 FL	*78.00 FL
14	1		*STEP UP UPPER GARNISH LH	Cracked	1,078.00 FL	*1,078.00 FL
15	1		*STEP UP LOWER GARNISH LH	Not Necessary	190.00 FL	*- FL
16	1		*STEP UP LOWER GARNISH METAL PLATE LH	Cracked	190.00 FL	*190.00 FL
17	1		*DOOR PILLAR LH (NPA)	Repair	0.00 FL	*- FL
18	1		*BONNET (NPA)	Repair	0.00 FL	*- FL
19	1		*FRONT BUMPER CLIPS	Necessary	35.00 FS	*35.00 FS
20	1		*CENTER GRILLE CLIPS	Not Necessary	25.00 FS	*- FS
21	1		*BONNET COMPANY STICKER	Necessary	400.00 FS	*200.00 FS
22	1		*FRONT BUMPER SIDE BRACKET LH	Cracked	198.00 FL	*198.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	10,242.00	8,250.00
- List Item Discount on L Items 25.00/25.00% (\$)	2,445.50	2,003.75
Total Parts (\$)	7,796.50	6,246.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS	New	1,400.00	750.00
2	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED & REPAIRED	New	1,400.00	1,000.00
3	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	90.00	40.00
4	TO REMOVE AND REPAIR / REFIT WIRING SYSTEM AT ACCIDENT DAMAGED AREA AND CHECK FOR ALL ELECTRICAL PROPER FUNCTION	New	90.00	40.00
5	TO REMOVE, REPLACE AND FOCUS HEADLAMP LH	New	50.00	0.00
6	TO REMOVE AND REFIT / REPLACE FRONT DOOR LH FITTING, TRIMMINGS, GARNISH, WINDOW GLASS AND LOCK MECHANISM	New	150.00	80.00
Gross Labour Cost (S\$)			3,180.00	1,910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >