



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SME 413L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT DOOR RH	TO REPAIR SEE LABOUR	1,533.20	-
1	FRONT FENDER RH	TO REPAIR SEE LABOUR	420.20	-
1	ROCKER PANEL RH	TO REPAIR SEE LABOUR	680.00	-
	LESS 10% DISCOUNT		-263.34	-
			2,370.06	-
	<u>LABOUR</u>			
	PANEL BEATING, WELDING, GRAZING, CUT, JOIN, STRAIGHTEN ALL AFFECTED PARTS. INCLUSIVE OF THE REPAIR OF FRONT DOOR RH, FRONT FENDER RH AND ROCKER PANEL RH.		1,200.00	100.00
	TO PUTTY, POLISH, SPRAY PAINT, WAX ALL AFFECTED PANELS.		1,200.00	600.00
	TUFF COAT.		250.00	40.00
	WIRING CHECK.	NOT NECESSARY	100.00	-
	REMOVE AND REFIX FRONT DOOR MECHANISM.	NOT NECESSARY	140.00	-
			2,890.00	740.00
	GRAND TOTAL		5,260.06	740.00
	RECOMMENDED COST OF REPAIRS			740.00

Report Ref No. CS/LIP22011409/Awy3e2

MARKET VALUE: \$88,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$35,995.00=NETT VALUE: \$52,005.00

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.