

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 5079K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	COVER, RR BUMPER ASSY (DISC 25%)	DEFORMED	525.40	394.05
2	PAD, RR BUMPER, RH & LH , 3 @\$12.00 (DISC 25%)	NECESSARY	24.00	18.00
2	PAD, RR BUMPER, RH & LH , 2 @\$4.30 (DISC 25%)	NECESSARY	8.60	6.45
2	PAD, RR BUMPER, RH & LH , 1 @\$4.30 (DISC 25%)	NECESSARY	8.60	6.45
3	PAD, RR BUMPER, CTR @\$12.00 (DISC 25%)	NECESSARY	36.00	27.00
2	SEAL, RR BUMPER ARM, RH & LH @\$12.30 (DISC 25%)	NECESSARY	24.60	18.45
10	CLIPS PIECE, FRT & RR BUMPER @\$4.80 (DISC 25%)	NECESSARY	48.00	36.00
1	GUARD, RR BUMPER, LOWER (DISC 25%)	DEFORMED	405.00	303.75
1	COVER, REAR FLOOR UNDER CENTER (DISC 25%)	CUT	249.10	186.83
1	NAME PLATE (HYBRID) , LUGGAGE COMPARTMENT DOOR (DISC 25%)	NECESSARY	59.10	44.33
1	NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT DOOR (DISC 25%)	NECESSARY	59.10	44.33
1	STRIDES LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 65558888 (SN)	NECESSARY	21.60	21.60
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	360.10	-
1	STOPPER, RR BUMPER, RH & LH	NOT NECESSARY	4.80	-
1	RETAINER, RR BUMPER, RH	NOT NECESSARY	143.60	-
1	RETAINER, RR BUMPER, LH	NOT NECESSARY	143.60	-
1	SEAL, RR BUMPER , RH	NOT NECESSARY	128.00	-
1	SEAL, RR BUMPER , LH	NOT NECESSARY	128.00	-
1	COVER, GUARD RR BUMPER LOWER	NOT NECESSARY	23.90	-
1	REAR BUMPER REFLECTOR ASSY, REFLEX, RH	NOT NECESSARY	42.20	-
1	REAR BUMPER REFLECTOR ASSY, REFLEX, LH	NOT NECESSARY	42.20	-
1	REAR BUMPER GROMMET SCREW	NOT NECESSARY	2.20	-
1	COVER, REAR FLOOR UNDER, RH	NOT NECESSARY	189.20	-
1	COVER, REAR FLOOR UNDER, LH	NOT NECESSARY	261.60	-
1	LENS & BODY, REAR COMBINATION LAMP , RH	NOT NECESSARY	367.30	-
1	LENS & BODY, REAR COMBINATION LAMP , LH	NOT NECESSARY	367.30	-
1	LENS & BODY, REAR COMBINATION LAMP, NO.2 RH	NOT NECESSARY	282.70	-

Report Ref No. NS/INC22011415/Rvy3m4



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	LENS & BODY, REAR COMBINATION LAMP, NO.2 LH	NOT NECESSARY	282.70	-
1	LAMP ASSY, REAR, RH	NOT NECESSARY	317.80	-
1	LAMP ASSY, REAR, LH	NOT NECESSARY	317.80	-
1	SENSOR REVERSE	NOT NECESSARY	180.00	-
1	ANTENNA, ELECTRICAL KEY	NOT NECESSARY	78.00	-
1	END PANEL SUB-ASSY, BODY LOWER BACK	NOT NECESSARY	707.10	-
1	SPARE TYRE PANEL , PAN, REAR FLOOR	NOT NECESSARY	630.30	-
1	SEALANT SIKAFLEX	NOT NECESSARY	37.00	-
1	TAIL GATE PANEL SUB-ASSY, BACK DOOR	NOT NECESSARY	1,238.40	-
1	TAIL GATE LOCK ASSY, BACK DOOR	NOT NECESSARY	505.50	-
1	TAIL GATE LOCK COVER, BACK DOOR	NOT NECESSARY	32.70	-
1	AUTO TAILGATE SYSTEM	NOT NECESSARY	2,520.00	-
1	TAIL GATE WEATHERSTRIP, BACK DOOR	NOT NECESSARY	402.50	-
1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	TO REPAIR SEE LABOUR	992.30	-
			12,205.70	1,115.04
	<u>LABOUR</u>			
	PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY.		1,014.00	300.00
	SPRAY PAINT.		1,476.00	300.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	TO CHECK WIRING AND SYSTEM FUNCTION.	NOT NECESSARY	120.00	-
	TO APPLY RUST-PROOFING ON AFFECTED AREA.	NOT NECESSARY	100.00	-
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.		120.00	40.00
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
			2,990.00	640.00
	GRAND TOTAL		15,195.70	1,755.04





Page No.:3 of 3

RECOMMENDED COST OF REPAIRS		1,755.04
(CONFIRMED)		

Report Ref No. NS/INC22011415/Rvy3m4

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser