

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22011416/APA3Q2**Date:** 30/05/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210030711
Claimant Vehicle No :	SFS1889A	Insured Vehicle No :	SMY9238L
Date of Loss:	12/11/2022	Nature of Claim:	TP
		Claim No:	6850795755SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFS1889A		
Make & Model:	AUDI A3, 999cc SEDAN 1.0 TFSI S TRONIC (LED) (A)	Engine No:	CHZ439381
Reg. Date:	20/06/2018 (Man. Year: 2018)	Chassis No:	WAUZZZ8V8J1057881
Colour:	White	Odometer:	107399 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,881.00	1,341.44	6,539.56	82.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,502.00	1,242.00	1,260.00	50.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,383.00	2,583.44	7,799.56	75.12
+ GST 8.00/8.00% (S\$)	830.64	206.68	623.96	75.12
Nett Amount (S\$)	11,213.64	2,790.12	8,423.52	75.12
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,092.12		

INSPECTION

Date of Assignment:	17/11/2022		
Date Inspected:	17/11/2022	Inspected At:	Premium Automobiles Pte Ltd (HQ) 55 UBI ROAD 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	2,432.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	195.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE -CENTER	Not Necessary	179.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT -LOWER CENTRE	Not Necessary	571.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT -RH	Not Necessary	318.00 FS	*- FS
6	1		*FRONT BUMPER TRIM COVER -RH	Not Necessary	182.00 FS	*- FS
7	1		*FRONT WHEEL HOUSING LINER ADAPTER -RH	Not Necessary	42.00 FS	*- FS
8	1		*RADIATOR GRILLE	Cut	1,578.00 FS	*1,262.40 FS
9	1		*RADIATOR GRILLE CLOSING ELEMENT	Not Necessary	210.00 FS	*- FS
10	1		*AIR CONDITIONER STICKER	Necessary	9.00 FS	*6.64 FS
11	1		*CAUTION SIGN STICKER	Necessary	16.00 FS	*12.40 FS
12	1		*RADIATOR AIR GUIDE GRILLE -RH	Not Necessary	210.00 FS	*- FS
13	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	847.00 FS	*- FS
14	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	211.00 FS	*- FS
15	1		*FRONT BUMPER REINFORCEMENT BEAM COVER	Not Necessary	136.00 FS	*- FS
16	1		*HORN LOW TONE -RH	Not Necessary	213.00 FS	*- FS
17	1		*RADIATOR AIR GUIDE -RH	Not Necessary	28.00 FS	*- FS
18	1		*RADIATOR AIR GUIDE OUTER SEAL -RH	Not Necessary	9.00 FS	*- FS
19	1		*RADIATOR AIR GUIDE UPPER CENTRE	Not Necessary	14.00 FS	*- FS
20	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Not Necessary	21.00 FS	*- FS
21	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
22	1		*SUNDRIES	Not Necessary	400.00 FS	*- FS
F=Franchise part. S=SpcNett.						
					Total Parts (S\$)	7,881.00 1,341.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	0.00
2	TO DISMANTLE AND RENEW FRONT BUMPER .RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
3	TO RESPRAY FRONT BUMPER	New	900.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			2,502.00	1,242.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >