



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBD 6831J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT FENDER	CRACKED	157.00	157.00
1	SET FRONT FORK	BENT	1,800.00	1,800.00
1	SET FRONT RUBBER SLIDER	SCRATCHED	186.00	186.00
1	HANDLE BAR	BENT	207.00	207.00
1	PAIR HANDLE BAR END BALANCER	SCRATCHED	64.00	64.00
1	PAIR HANDLE BAR GRIP	NOT NECESSARY	82.00	-
1	PAIR WING MIRROR	SCRATCHED	190.00	190.00
1	R/H BRAKE LEVER W/BRAKE RESERVOIR	SCRATCHED	394.00	394.00
1	HEADLAMP	BROKEN	482.00	482.00
1	HEAD FAIRING	BROKEN	392.00	392.00
1	HEAD FAIRING INNER PANEL	DEFORMED	221.00	221.00
1	FRONT WINDSHIELD	BROKEN	257.00	257.00
1	INSTRUMENT PANEL	NOT NECESSARY	762.00	-
1	RADIATOR	NOT NECESSARY	929.00	-
1	FUEL TANK	BUCKLED	957.00	856.00
1	R/H RIDER FOOT REST W/BACKET	BROKEN	242.00	242.00
1	R/H FOOT BRAKE PEDAL	BENT	67.00	67.00
1	SET REAR SWINGARM RUBBER SLIDER	SCRATCHED	186.00	186.00
1	R/H REAR SIGNAL LAMP	SCRATCHED	47.00	47.00
1	R/H REAR SIDE FAIRING	SCRATCHED	220.00	220.00
	LESS 10% DISCOUNT		-	-596.80
			7,842.00	5,371.20
<u>SPECIAL NETT ITEMS</u>				
1	FRONT NO. PLATE STICKER (SN)	NECESSARY	25.00	25.00
1	FRONT WHEEL RIM (SN)	DISTORTED	900.00	450.00
1	FRONT TYRE (SN)	NOT NECESSARY	360.00	-
1	REAR WHEEL RIM (SN)	NOT NECESSARY	450.00	-
1	REAR TYRE (SN)	NOT NECESSARY	360.00	-
1	REAR BOX W/BASE BRACKET (SN)	SCRATCHED	590.00	450.00
			2,685.00	925.00

Report Ref No. CS3/SMR22002686/Tny3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>LABOUR</u>			
	TO DISMANTLE AND REPAIR DAMAGED PARTS.		1,100.00	300.00
	TO CHECK WIRING.		60.00	30.00
	TO REALIGN FRONT FORK.		200.00	100.00
	TO REMOVE AND REINSTALL FUEL TANK.		120.00	50.00
	TO PUTTY AND SPRAY-PAINT OF AFFECTED AREAS.		500.00	300.00
			1,980.00	780.00
	GRAND TOTAL		12,507.00	7,076.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,650.00

Report Ref No. CS3/SMR22002686/Tny3e2-1

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.