



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 699D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER FRT (DISC 30%) (CONSISTENT)	CRACKED	602.60	421.82
10	CLIPS PIECE ,FRT & RR BUMPER @\$4.80 (DISC 30%) (CONSISTENT)	NECESSARY	48.00	33.60
1	BRACKET ,FR BUMPER (DISC 30%)(CONSISTENT)	CRACKED	126.10	88.27
1	COVER ,FR BUMPER HOLE LH (DISC 30%)(CONSISTENT)	MISSING	21.40	14.98
1	BUMPER GRILLE SUB-ASSY ,LOWER (DISC 30%) (CONSISTENT)	CRACKED	389.90	272.93
1	EMBLEM FRONT (DISC 30%)(CONSISTENT)	NECESSARY	98.70	69.09
1	LENS & BODY ,FR TURN LH (DISC 10%)(CONSISTENT)	SCRATCHED	581.40	523.26
1	NUMBER PLATE FRAME (SN)(CONSISTENT)	BENT	25.00	25.00
1	NUMBER PLATE (SN)(CONSISTENT)	BENT	35.00	35.00
1	BUMPER SUPPORT F/LH (CONSISTENT)	NOT NECESSARY	86.20	-
1	BUMPER ENERGY ABSORBER FRT (CONSISTENT)	NOT NECESSARY	97.60	-
1	BUMPER REINFORCEMENT FRT (CONSISTENT)	NOT NECESSARY	567.90	-
1	ARM SUB-ASSY ,FR BUMPER LH (CONSISTENT)	NOT NECESSARY	284.00	-
1	ARM SUB-ASSY ,FR BUMPER RH(CONSISTENT)	NOT NECESSARY	284.00	-
1	FOG LAMP LH (CONSISTENT)	NOT NECESSARY	319.30	-
1	GRILLE RADIATOR (CONSISTENT)	NOT NECESSARY	389.30	-
1	GRILLE ,RADIATOR LOWER NO.2(CONSISTENT)	NOT NECESSARY	118.30	-
1	BUMPER LIP FRT (CONSISTENT)	NOT NECESSARY	182.70	-
1	BUMPER FRT ABSORBER LOWER (CONSISTENT)	NOT NECESSARY	159.30	-
1	UNDER COVER CENTER (CONSISTENT)	NOT NECESSARY	511.20	-
1	UNDER COVER SIDE /LH (CONSISTENT)	NOT NECESSARY	52.50	-
1	SUPPORT SUB-ASSY (CONSISTENT)	NOT NECESSARY	1,839.70	-
1	HEAD LAMP LH (CONSISTENT)	NOT NECESSARY	1,075.40	-
1	SUPPORT RADIATOR ,LH (CONSISTENT)	NOT NECESSARY	23.40	-
			7,918.90	1,483.95
	<u>LABOUR</u>			
	PANEL BEATING & BODY WORK .		676.00	200.00
	SPRAY PAINT.		738.00	200.00
	TO WASH AND VACUUM .	NOT NECESSARY	60.00	-

Report Ref No. CC4/ASM22011420/Rpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK WIRING AND SYSTEM FUNCTION .	NOT NECESSARY	120.00	-
	TO APPLY RUST-PROOFING ON AFFECTED AREA .	NOT NECESSARY	100.00	-
	TO REPLACE SUNDRY PARTS .	NOT NECESSARY	100.00	-
			1,794.00	400.00
GRAND TOTAL			9,712.90	1,883.95
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,000.00

Report Ref No. CC4/ASM22011420/Rpa3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.