

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22011425/AYA3Q2**Date:** 17/05/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900115562
Claimant Vehicle No :	SJY7278U	Insured Vehicle No :	SCX6768S
Date of Loss:	07/11/2022	Nature of Claim:	TP
		Claim No:	4799447018SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJY7278U		
Make & Model:	KIA CERATO FORTE KOUP, 1.6 SX ABS D/AB SR (A)	Engine No:	G4FCAH226944
Reg. Date:	22/07/2010 (Man. Year: 2010)	Chassis No:	KNAFW611MA5278828
Colour:	Red	Odometer:	191921 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,146.40	3,397.20	2,749.20	44.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,570.00	1,630.00	1,940.00	54.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	9,716.40	5,027.20	4,689.20	48.26
Approved Total (Overridden) (\$\$)		4,000.00		
(\$\$)	9,716.40	4,000.00	5,716.40	58.83
+ GST 8.00/8.00% (\$\$)	777.31	320.00	457.31	58.83
Nett Amount (\$\$)	10,493.71	4,320.00	6,173.71	58.83
+ Loss of Use (6.0 x S\$60.00/day) (\$\$)		360.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		4,682.00		
Global Sum Settlement (\$\$)		4,600.00		

INSPECTION

Date of Assignment:	11/11/2022	
Date Inspected:	11/11/2022	Inspected At: Success United Pte Ltd (HQ) 2 Kaki Bukit Ave 2 #01-33, Kaki Bukit AutoHub Singapore 417921
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Deformed	974.00 FL	*974.00 FL
2	2		*REAR BOOT LID HINGE L/R	Not Necessary	196.00 FL	*- FL
3	1		*REAR BOOT LAMP RH	Not Necessary	356.00 FL	*- FL
4	1		*REAR KIA LOGO	Necessary	58.00 FL	*58.00 FL
5	1		*REAR BOOT MECHANISM LOCK	Damaged	181.00 FL	*181.00 FL
6	1		*REAR BOOT WEATHERSTRIP	Cut	115.00 FL	*115.00 FL
7	2		*REAR LAMP ASSY L/R	Not Necessary	738.00 FL	*- FL
8	1		*REAR BUMPER ASSY	Deformed	810.00 FL	*689.00 FL
9	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
10	1		*REAR REVERSE SENSOR	Damaged	241.00 FL	*241.00 FL
11	1		*REAR BUMPER LOWER SPOILER	Deformed	325.00 FL	*325.00 FL
12	1		*REAR NO PLATE LAMP	Not Necessary	45.00 FL	*- FL
13	1		*REAR BUMPER INNER SPONGE	Cracked	198.00 FL	*198.00 FL
14	1		*REAR BUMPER REINFORCEMENT	Cracked	372.00 FL	*372.00 FL
15	1		*REAR END PANEL	Dented	418.00 FL	*418.00 FL
16	1		*REAR BUMPER REFLECTOR LAMP RH	Cracked	42.00 FL	*42.00 FL
17	1		*REAR EXHAUST SILENCER BOX ASSY	Not Necessary	686.00 FL	*- FL
18	1		*REAR END PANEL INNER TOP GARNISH	Deformed	65.00 FL	*65.00 FL
19	1		*REAR SPARE TYRE PANEL	Repair	896.00 FL	*- FL
20	1		*REAR NO PLATE W/FRAME	Cracked	75.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,821.00	3,768.00
- List Item Discount on L Items 10.00/10.00% (S\$)	674.60	370.80
Total Parts (S\$)	6,146.40	3,397.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE REPAIR AND REPLACED DAMAGED BODYPARTS ,REALIGN BODYWORK & WHERE CONSISTENT TO THE ACCIDENT	New	1,800.00	800.00
2	TO REMOVE,REARRANGE ELECTRICAL WIRINGS, CHECK LIGHTING	New	120.00	30.00
3	TO REMOVE,REINSTALL REAR EXHAUST SILENCER BOX	New	150.00	0.00
4	TO PUTTY & RESPRAY PAINTING OF BOOT LID ,BUMPER ,END PANEL ,TYRE PANEL	New	1,500.00	800.00
Gross Labour Cost (\$\$)			3,570.00	1,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >