

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III22011436/RYA3Q2**Date:** 28/07/2023**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MPC0004850_01

Claimant Vehicle No : SHF188R **Insured Vehicle No :** SMU9387K

Date of Loss: 15/11/2022 Nature of Claim: TP Claim No: MPC2022D0008685

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHF188R**
 Make & Model: TOYOTA PRIUS, 1.8 5DR HATCHBACK (A) Engine No: 2ZR2G30640
 Reg. Date: 26/12/2019 (Man. Year: 2019) Chassis No: JTDKB3FUX03090688
 Colour: Maroon Odometer: 216783 km
 Engine Capacity: 1798 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Sailun 6 mm Rear Left Side: Sailun 6 mm
 Front Right Side: Sailun 6 mm Rear Right Side: Sailun 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,866.80	1,396.22	5,470.58	79.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,032.00	790.00	2,242.00	73.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	9,898.80	2,186.22	7,712.58	77.91
+ Loss of Use (7.0 x S\$40.00/day) (S\$)		280.00		
+ Car Rental (7.0 x S\$87.74/day) (S\$)		614.18		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,082.40		

INSPECTION

Date of Assignment: 15/11/2022

Date Inspected: 15/11/2022 Inspected At:

Strides Automotive Services Pte Ltd (Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Jul 2023)
Parts:	144	TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHF188R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*COVER ,RR BUMPER ASSY (DISC 25%)	Cracked	525.40 F	*394.05 F
2	2	*PAD ,RR BUMPER ,RH & LH ,3 (DISC 25%)	Necessary	24.00 F	*18.00 F
3	1	*PAD ,RR BUMPER ,RH & LH ,2 (DISC 25%) (2 PCS)	Necessary	8.60 F	*6.45 F
4	1	*PAD ,RR BUMPER ,RH & LH ,1 (DISC 25%) (2 PCS)	Necessary	8.60 F	*6.45 F
5	3	*PAD ,RR BUMPER CTR (DISC 25%)	Necessary	36.00 F	*27.00 F
6	1	*SEAL RR BUMPER ARM ,RH & LH (DISC 25%) (2 PCS)	Necessary	24.60 F	*18.45 F
7	10	*CLIPS PIECE ,FRT & RR BUMPER (DISC 25%)	Necessary	48.00 F	*36.00 F
8	1	*GUARD ,RR BUMPER ,LOWER (DISC 25%)	Dented	405.00 F	*303.75 F
9	1	*COVER ,GUARD RR BUMPER LOWER (DISC 25%)	Distorted	23.90 F	*17.93 F
10	1	*REAR BUMPER REINFORCEMENT (DISC 25%)	Dented	360.10 F	*270.08 F
11	1	*NAME PLATE (HYBRID) LUGGAGE COMPARTMENT (DISC 25%)	Necessary	59.10 F	*44.33 F
12	1	*NAME PLATE (PRIUS)LUGGAGE COMPARTMEN (DISC 25%)	Necessary	59.10 F	*44.33 F
13	1	*SENSOR REVERSE (SN)	Necessary	180.00 F	*180.00 F
14	1	*STRIDES LOGO (SN)	Necessary	7.80 F	*7.80 F
15	1	*STICKER DECAL 65558888 (SN)	Necessary	21.60 F	*21.60 F
16	1	*REAR BUMPER REINFORCEMENT	Not Necessary	360.10 F	*- F
17	2	*STOPPER ,RR BUMPER ,RH & LH	Not Necessary	4.80 F	*- F
18	1	*RETAINER ,RR BUMPER ,RH	Not Necessary	143.60 F	*- F
19	1	*RETAINER ,RR BUMPER ,LH	Not Necessary	143.60 F	*- F
20	1	*SEAL ,RR BUMPER ,RH	Not Necessary	128.00 F	*- F
21	1	*SEAL ,RR BUMPER ,LH	Not Necessary	128.00 F	*- F
22	1	*REAR BUMPER REFLECTOR ASSY ,REFLEX ,RH	Not Necessary	42.20 F	*- F
23	1	*REAR BUMPER REFLECTOR ASSY ,REFLEX ,LH	Not Necessary	42.20 F	*- F
24	1	*REAR BUMPER GROMMET SCREW	Not Necessary	2.20 F	*- F
25	1	*COVER ,REAR FLOOR UNDER ,RH	Not Necessary	189.20 F	*- F
26	1	*COVER ,REAR FLOOR UNDER ,LH	Not Necessary	261.60 F	*- F
27	1	*COVER ,REAR FLOOR UNDER CENTER	Not Necessary	249.10 F	*- F
28	1	*SENSOR REVERSE	Not Necessary	180.00 F	*- F
29	1	*ANTENNA ,ELECTRICAL KEY	Not Necessary	78.00 F	*- F
30	1	*END PANEL SUB-ASSY ,BODY LOWER BACK	Not Necessary	707.10 F	*- F
31	1	*SEALANT SIKAFLEX	Not Necessary	37.00 F	*- F
32	1	*TAIL GATE PANEL SUB-ASSY ,BACK DOOR	Not Necessary	1,238.40 F	*- F
33	1	*TAIL GATE BACK DOOR OUTSIDE GARNISH SUB	Not Necessary	992.30 F	*- F
34	1	*NAME PLATE (HYBRID) LUGGAGE COMPARTMENT	Not Necessary	59.10 F	*- F
35	1	*NAME PLATE (PRIUS) LUGGAGE COMPARTMENT	Not Necessary	59.10 F	*- F
36	1	*STRIDES LOGO	Not Necessary	7.80 F	*- F
37	1	*STICKER DECAL 6555 8888	Not Necessary	21.60 F	*- F

F=Franchise part.

Total Parts (\$\$) 6,866.80 1,396.22

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	876.00	300.00
2	SPRAY PAINT	New	1,656.00	450.00
3	TO WASH AND VACUUM	New	60.00	0.00
4	TO CHECK WIRING AND SYSTEM FUNCTION	New	120.00	0.00
5	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	100.00	0.00
6	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	40.00
7	TO REPLACE SUNDRY PARTS	New	100.00	0.00
Gross Labour Cost (S\$)			3,032.00	790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >