

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22011443/UVY3Q2
Date: 18/11/2022

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00071592203
Claimant Vehicle No :	SLP2829L	Insured Vehicle No :	GBH4453J
Date of Loss:	07/11/2022	Nature of Claim:	TP
		Claim No:	SNM22D208031/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP2829L		
Make & Model:	PEUGEOT 308, 1.2 SW ALLURE PURETECH 2WD S/R. (A)	Engine No:	10XTA40460384
Reg. Date:	30/05/2017 (Man. Year: 2016)	Chassis No:	VF3LPHNYWGS255622
Colour:	Blue	Odometer:	135671 km
Engine Capacity:	1199 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Goodyear 7 mm	Rear Left Side:	Goodyear 7 mm
Front Right Side:	Goodyear 7 mm	Rear Right Side:	Goodyear 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,154.50	2,092.50	1,062.00	33.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,460.00	770.00	690.00	47.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,614.50	2,862.50	1,752.00	37.97
Approved Total (Overridden) (S\$)		2,200.00		
Nett Amount (S\$)	4,614.50	2,200.00	2,414.50	52.32

INSPECTION

Date of Assignment:	14/11/2022	
Date Inspected:	15/11/2022 Inspected At:	PROMPT AUTO SOLUTIONS PTE LTD (Premier) 8 KAKI BUKIT AVE 4, #02-37 PREMIER@KAKI BUKIT Singapore 415875
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 17 Nov 2022)	
Parts:	N/A	PEUGEOT 308 1.2 SW ALLURE PURETECH 2WD S/R. (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLP2829L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Deformed	1,550.00 FL	*1,550.00 FL
2	1		*REAR BUMPER LOWER GARNISH	Grazed	457.00 FL	*355.00 FL
3	1		*REAR BUMPER TOWING COVER	Not Necessary	17.00 FL	*- FL
4	1		*REAR BUMPER RH SIDE REVERSE SENSOR	Not Necessary	191.00 FL	*- FL
5	1		*REAR BUMPER RH CENTRE REVERSE SENSOR	Shorted	191.00 FL	*191.00 FL
6	1		*REAR BUMPER LH SIDE REVERSE SENSOR	Not Necessary	191.00 FL	*- FL
7	1		*REAR BUMPER LH CENTRE REVERSE SENSOR	Not Necessary	191.00 FL	*- FL
8	1		*REAR BUMPER REVERSE SENSORS HOLDER	Necessary	88.00 FL	*88.00 FL
9	1		*REAR BUMPER RH SIDE RETAINER	Not Necessary	63.00 FL	*- FL
10	1		*REAR BUMPER LH SIDE RETAINER	Not Necessary	63.00 FL	*- FL
11	1		*REAR BUMPER INNER CENTRE BRACKET	Cracked	91.00 FL	*91.00 FL
12	1		*REAR BUMPER REINFORCEMENT	Repair	342.00 FL	*- FL
13	1		*SET REAR BUMPER CLIPS	Necessary	70.00 FL	*50.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	3,505.00	2,325.00
- List Item Discount on L Items 10.00/10.00% (\$)	350.50	232.50
Total Parts (\$)	3,154.50	2,092.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES ON AFFECTED AREAS AND REPLACED PARTS AS LISTED	New	600.00	300.00
2	RESPRAY AFFECTED AREAS AND PARTS	New	600.00	400.00
3	CHECK WIRING AND LIGHTING SYSTEM	New	80.00	20.00
4	APPLY ANTI RUST CHEMICAL COATING	New	80.00	0.00
5	REMOVE AND REPLACE REAR BUMPER REVERSE SENSORS AND HOLDERS	New	100.00	50.00
Gross Labour Cost (\$\$)			1,460.00	770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >