Adjuster Report 3/8/23, 5:13 PM

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/HLA22011444/AWY3E2

Date:

08/03/2023

REFERENCE

Handling Insurer:

HL Assurance Pte Ltd

Policy No:

MP319137

Claimant Vehicle No:

SJD2503M

Insured Vehicle No:

SNB9154D

Date of Loss:

09/11/2022

Nature of Claim:

TP

Claim No:

MPC03822/GN

Yes

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SJD2503M

Make & Model:

MAZDA 3, 1.5 (A)

14/03/2008 (Man. Year: 2007)

Engine No: Chassis No: Odometer:

Z6594718 JM6BK106280368098 206268 km

Reg. Date: Colour:

Black

Engine Capacity:

1598 cc Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable): **Engine Modification:**

Yes

No

Footbrake (Serviceable):

Pre-accident Condition:

Handbrake (Serviceable): **CONDITION OF TYRES**

Front Tyre Size:

205/55 R16

Yes

Rear Tyre Size: Rear Left Side:

205/55 R16

Front Left Side: Front Right Side: Dunlop 6 mm Dunlop 6 mm

Rear Right Side:

Dunlop 6 mm Dunlop 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | | Repairer's | Adjuster's | Difference | Diff % |
|---------------------|-----------------------------------|------------|------------|------------|--------|
| Parts | | 4,094.12 | 2,679.32 | 1,414.80 | 34.56 |
| Miscellaneous Items | | 0.00 | 0.00 | 0.00 | |
| Labour | | 1,660.00 | 1,030.00 | 630.00 | 37.95 |
| Paintwork Labour | | 0.00 | 0.00 | 0.00 | |
| Towing | | 0.00 | 0.00 | 0.00 | |
| | Calculated Gross Total (S\$) | 5,754.12 | 3,709.32 | 2,044.80 | 35.54 |
| | Approved Total (Overridden) (S\$) | | 2,950.00 | | |
| | (S\$) | 5,754.12 | 2,950.00 | 2,804.12 | 48.73 |
| | + GST 8.00/8.00% (S\$) | 460.33 | 236.00 | 224.33 | 48.73 |
| | Nett Amount (S\$) | 6,214.45 | 3,186.00 | 3,028.45 | 48.73 |

INSPECTION

Date Inspected:

Date of Assignment:

15/11/2022

15/11/2022

Inspected At:

Sin Hwee Motor Pte Ltd (HQ) Blk 3023A, Ubi Road 1, #01-59

Singapore 408717

Estimated Period of Repair:

5.0 days

Manager:

XinYu

Adjuster: **ADRIAN LING**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

3/8/23, 5:13 PM Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Mar 2023)

Parts: 144 MAZDA 3 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJD2503M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|------|---------|---------------|---------------------------|-----------------------------------|------------|------------|
| 1 | 1 | | *L/H FRONT FENDER | Dented | 489.55 FL | *489.55 FL |
| 2 | 1 | | *FRONT FENDER INNER COVER | Deformed | 189.44 FL | *189.44 FL |
| 3 | 1 | | *FRONT BUMPER | Torn | 889.44 FL | *889.44 FL |
| 4 | 1 | | *BUMPER LOWER LID | Not Necessary | 487.00 FL | *- FL |
| 5 | 1 | | *KNUCKLE ARM | Damaged | 468.00 FL | *468.00 FL |
| 6 | 1 | | *KNUCKLE ARM BEARING | Damaged | 278.00 FL | *278.00 FL |
| 7 | 1 | | *LOWER ARM | Bent | 397.22 FL | *397.22 FL |
| 8 | 1 | | *ABSORBER | Not Necessary | 347.00 FL | *- FL |
| 9 | 1 | | *HEADLAMP L/H | Not Necessary | 897.00 FL | *-FL |
| 10 | 1 | | *SPORT RIM | Cut | 450.00 FS | *450.00 FS |
| 11 | 10 | | *BUMPER CLIP | Necessary | 45.00 FS | *30.00 FS |
| 12 | 10 | | *FENDER COVER CLIP | Necessary | 45.00 FS | *30.00 FS |
| F=Fr | anchise | part. S=SpcNe | ett. L=ListItemDisc. | | | |
| | | | | Sub Total (S\$) | 4,982.65 | 3,221.65 |
| | | | - List Item Discou | int on L Items 20.00/20.00% (S\$) | 888.53 | 542.33 |
| | | | | Total Parts (S\$) | 4,094.12 | 2,679.32 |
| | | | | | | |

Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

3/8/23, 5:13 PM

| No | Particulars | Lab.Type | Repairer's | Amount |
|-----|---|--------------|------------|----------|
| Lab | our Items | | | |
| 1 | COMPUTERIZED 4 WHEELS ALIGNMENT | New | 80.00 | 80.00 |
| 2 | TO DISMOUNT AND REPLACE FRONT L/H UNDER CARRIAGE. TO PRESS AND JACK WHEELS BEARING $$ | New | 180.00 | 150.00 |
| 3 | TO KNOCK INNER BRACKETS AND REPLACE / ALIGN AFFECTED PARTS ATO SYMMETRICAL SPEC | New | 650.00 | 400.00 |
| 4 | TO SPRAY PAINT FRONT BUMPER, LOWER LIP AND FENDER | New | 750.00 | 400.00 |
| | Gross Labour | r Cost (S\$) | 1,660.00 | 1,030.00 |
| | Report was unsubmitted during this pri | nt-out. | | |

< END OF ESTIMATES >