

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22011445/EQY3Q2**Date:** 19/01/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00133782101
Claimant Vehicle No :	PC216P	Insured Vehicle No :	YQ2937Z
Date of Loss:	08/11/2022	Nature of Claim: TP	Claim No: SNM22D208044/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC216P		
Make & Model:	GOLDEN DRAGON XML6957J14B, 6.7 D TURBO (M)	Engine No:	ISBE422521972391
Reg. Date:	01/04/2011 (Man. Year: 2010)	Chassis No:	LL3BECDH9AA014494
Colour:	Multi-colour	Odometer:	103817 km
Engine Capacity:	6693 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	285/80 R22.5	Rear Tyre Size:	285/80 R22.5
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	29,176.60	18,485.00	10,691.60	36.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,200.00	6,450.00	1,750.00	21.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	37,376.60	24,935.00	12,441.60	33.29
Approved Total (Overridden) (S\$)		19,950.00		
Nett Amount (S\$)	37,376.60	19,950.00	17,426.60	46.62

INSPECTION

Date of Assignment:	15/11/2022		
Date Inspected:	15/11/2022	Inspected At:	5 Old Toh Tuck Rd Repairer: A T Auto Consultant (HQ)
Estimated Period of Repair:	12.0 days		

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 18 Jan 2023)	
Parts:	N/A	GOLDEN DRAGON XML6957J14B 6.7 D TURBO (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC216P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	2,850.00 FL	*2,500.00 FL
2	1		*FRONT BUMPER BRACKET	Bent	1,250.00 FL	*400.00 FL
3	1		*FRONT PANEL	Broken	3,650.00 FL	*3,200.00 FL
4	1		*FRONT INNER SUPPORT PANEL (NPA)	Repair	0.00 FL	*- FL
5	2		*HEAD LAMP RH/LH	Broken	3,378.00 FL	*3,060.00 FL
6	1		*REAR ENGINE HOOD	Dented	2,800.00 FL	*2,800.00 FL
7	1		*REAR ENGINE HOOD LOCK	Bent	485.00 FL	*200.00 FL
8	1		*REAR BUMPER	Broken	2,356.00 FL	*2,100.00 FL
9	1		*REAR BUMPER BRACKET	Bent	480.00 FL	*400.00 FL
10	1		*REAR BUMPER REFLECTOR LH/RH	O/S Broken	360.00 FL	*110.00 FL
11	1		*REAR TAIL LAMP CORNER PANEL RH/LH	O/S Broken	7,300.00 FL	*2,200.00 FL
12	1		*REAR REVERSE LAMP RH	Not Necessary	135.00 FL	*- FL
13	1		*REAR INNER SUPPORT FRAME	Repair	2,400.00 FL	*- FL
14	1		*EXHAUST TAIL PIPE	Bent	1,280.00 FL	*1,280.00 FL
15	1		*HYDRALIC PRESSURE PUMP	Not Necessary	650.00 FL	*- FL
16	1		*COOLANT FAN PULLEY	Bent	780.00 FL	*780.00 FL
17	3		*COOLANT FAN PULLEY BELTS	Cut (1 PCS ONLY)	840.00 FL	*240.00 FL
18	1		*REAR COMPARTMENT PANEL RH (NPA)	Repair	0.00 FL	*- FL
19	6		*WINDSCREEN SEALANT	Necessary	180.00 FS	*180.00 FS
20	1		*FRONT & REAR BUMPER PLATE	Broken	100.00 FS	*100.00 FS
21	1		*FRONT COMPANY LOGO	Necessary	280.00 FS	*200.00 FS
22	1		*REAR COMPANY LOGO	Necessary	560.00 FS	*500.00 FS
23	1		*REAR BUMPER NUMBER PLATE LED LAMP	Broken	180.00 FL	*180.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	32,294.00	20,430.00
- List Item Discount on L Items 10.00/10.00% (S\$)	3,117.40	1,945.00
Total Parts (S\$)	29,176.60	18,485.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING FOR REPLACE AND REPAIR AFFECTED PARTS	New	3,600.00	3,000.00
2	SPRAY PAINTING ON AFFECTED AREA FOR 3 COLOURS	New	3,200.00	2,500.00
3	REMOVE & REINSTALL FRONT WINDSCREEN	New	800.00	800.00
4	WIRING CHARGES & TESTING COMMISSIONING	New	200.00	100.00
5	APPLY PUTTY AND ANTI-CORROSION TO AFFECTED PARTS	New	400.00	50.00
Gross Labour Cost (S\$)			8,200.00	6,450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >