

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22011446/UNY3Q2**Date:** 22/11/2022REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00101742207

**Claimant Vehicle
No :** SLS3247T**Insured Vehicle
No :** GBA5363R

Date of Loss: 12/11/2022

Nature of Claim: TP

Claim
No: SNM22D208162/C02/IRENEDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLS3247T**

Make & Model: TOYOTA WISH, 1.8 (A)

Engine No: 2ZR0A08856

Reg. Date: 20/09/2017 (Man. Year: 2017)

Chassis No: JTDGG20WX0J007834

Colour: White

Odometer: 51513 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,234.75	7,188.57	3,046.18	29.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,500.00	2,140.00	1,360.00	38.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	13,734.75	9,328.57	4,406.18	32.08
Approved Total (Overridden) (\$\$)		7,400.00		
(\$\$)	13,734.75	7,400.00	6,334.75	46.12
+ GST 7.00/7.00% (\$\$)	961.43	518.00	443.43	46.12
Nett Amount (\$\$)	14,696.18	7,918.00	6,778.18	46.12

INSPECTION

Date of Assignment: 15/11/2022

Date Inspected: 15/11/2022 Inspected At:

BLK 9006 TAMPINES ST 93 #01-200 SINGAPORE
528840

Repairer: Falcon Air Auto Services Pte Ltd (HQ)

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Nov 2022)
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLS3247T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE GLASS MOULDING -TOP	Necessary	89.00 FL	*89.00 FL
2	1		*TAILGATE GLASS MOULDING -LOWER	Necessary	89.00 FL	*89.00 FL
3	2		*TAILGATE GLASS SIDE MOULDING	Necessary	178.00 FL	*178.00 FL
4	1		*TAILGATE	Badly Dented	1,694.00 FL	*1,694.00 FL
5	1		*TAILGATE LOGO EMBLEM	Necessary	89.00 FL	*89.00 FL
6	1		*TAILGATE ELEGANCE EMBLEM	Necessary	134.00 FL	*105.00 FL
7	1		*TAILGATE VALVEMATIC EMBLEM	Necessary	93.00 FL	*93.00 FL
8	1		*TAILGATE CHROME GARNISH	Cracked	498.00 FL	*498.00 FL
9	2		*REAR NUMBER PLATE LAMP	Not Necessary	150.00 FL	*- FL
10	1		*TAILGATE LAMP	N/S Cracked / O/SNot Necessary	876.00 FL	*438.00 FL
11	2		*TAILGATE LAMP SPONGE	Not Necessary	90.00 FL	*- FL
12	1		*TAILGATE LOCK	Dented / Shorted	469.00 FL	*469.00 FL
13	1		*TAILGATE TRIM BOARD	Deformed / Torn	597.00 FL	*597.00 FL
14	1		*REAR WIPER MOTOR	Not Necessary	895.00 FL	*- FL
15	1		*TAILGATE OUTER HANDLE	Not Necessary	125.00 FL	*- FL
16	1		*TAILGATE WEATHERSTRIP	Twisted	364.00 FL	*364.00 FL
17	1		*REAR BUMPER	Dented	894.00 FL	*721.10 FL
18	2		*REAR BUMPER SIDE RETAINER	Bent	196.00 FL	*196.00 FL
19	1		*TAILGATE ANTENNA SENSOR	Cracked	149.00 FL	*149.00 FL
20	1		*REAR END PANEL	Badly Dented / Bent	597.00 FL	*597.00 FL
21	2		*REAR END PANEL BRACKET	Not Necessary	292.00 FL	*- FL
22	1		*REAR END PANEL GARNISH	Twisted	398.00 FL	*398.00 FL
23	2		*REAR FENDER INNER TRIM	Deformed / Cracked	1,794.00 FL	*1,794.00 FL
24	1		*SPARE TYRE BOARD	Not Necessary	769.00 FL	*- FL
25	2		*SPARE TYRE BOARD -SIDE	Not Necessary	394.00 FL	*- FL
26	1		*TAILGATE GLASS INNER SEAL	Necessary	80.00 FS	*40.00 FS
27	1		*TAILGATE GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
28	1		*TAILGATE SEALANT	Necessary	100.00 FS	*50.00 FS
29	5		*TAILGATE CHROME GARNISH CLIPS	Not Necessary	25.00 FS	*- FS
30	1		*REAR NUMBER PLATE	Scratched	45.00 FS	*40.00 FS
31	1		*SET REVERSE CAMERA	Shorted	500.00 FS	*300.00 FS
32	1		*SET TAILGATE TRIM BOARD CLIPS	Necessary	50.00 FS	*50.00 FS
33	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*50.00 FS
34	1		*SET REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
35	10		*REAR END PANEL GARNISH CLIP	Not Necessary	50.00 FS	*- FS
36	20		*REAR FENDER INNER TRIM CLIP	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,213.00	9,328.10
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,978.25	2,139.53
Total Parts (\$\$)	10,234.75	7,188.57

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TRANSFER TAILGATE PARTS	New	150.00	60.00
2	RESPRAY ANTI RUST	New	150.00	60.00
3	APPLY BODY SEALANT TO CAR JOINTS	New	150.00	50.00
4	INSTALL REVERSE CAMERA }	New	100.00	50.00
5	INSTALL REVERSE SENSOR }	New	150.00	0.00
6	TO CHECK WIRING	New	50.00	20.00
7	TO REMOVE INNER TRIM TO FACILITATE REPAIRS N FIX BACK	New	200.00	80.00
8	TO REMOVE NECESSARY PARTS TO CUT OUT END PANEL REPAIR END PANEL ,REWELD END PANEL ,REPLACE ACCIDENT DAMAGE PARTS AND ALIGN THE SAME	New	1,200.00	800.00
9	TO PUTTY AND RESPRAY ACCIDENT DAMAGE AREAS	New	1,200.00	900.00
10	TRANSFER REAR WINDSCREEN GLASS	New	150.00	120.00
Gross Labour Cost (\$\$)			3,500.00	2,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >