

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22011447/RQY3Q2**Date:** 01/02/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00247512200		
Claimant Vehicle No :	SLT8836E	Insured Vehicle No :	SKH3005U		
Date of Loss:	05/11/2022	Nature of Claim:	TP	Claim No:	SNM22D208080/C02/KHONGLH

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SLT8836E</b>	Engine No:	F852H587B38A15A
Make & Model:	BMW X1 SDRIVE18I, 1.5 LED NAV (A)	Chassis No:	WBAJG12070EE61718
Reg. Date:	16/11/2017 (Man. Year: 2017)	Odometer:	92206 km
Colour:	Grey		
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	225/50 R18	Rear Tyre Size:	225/50 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,313.80	4,187.90	125.90	2.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,158.00	2,629.00	529.00	16.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>7,471.80</b>	<b>6,816.90</b>	<b>654.90</b>	<b>8.76</b>
<b>+ GST 7.00/7.00% (S\$)</b>	523.03	477.18	45.85	8.77
<b>Nett Amount (S\$)</b>	<b>7,994.83</b>	<b>7,294.08</b>	<b>700.75</b>	<b>8.77</b>

**INSPECTION**

Date of Assignment:	15/11/2022	Performance Motors Limited (Alexandra)
Date Inspected:	05/12/2022 Inspected At:	303 Alexandra Road, Sime Darby Performance Centre
Estimated Period of Repair:	4.0 days	Singapore 159941

**Adjuster:** MOHD RASUL**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 31 Jan 2023)
Parts:	M1-SUV	BMW X1 SDRIVE18I 1.5 LED NAV (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLT8836E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
2	1		*RH FOG LAMP BRACKET	Not Necessary	125.90 FS	*- FS
3	1		*FRT BUMPER PANEL PRIMED (PDC/PMA)	Scratched	894.85 FS	*894.85 FS
4	1		*RH OPEN GRID (X LINE)	Scratched	96.95 FS	*96.95 FS
5	1		*FRT BUMPER PANEL LOWER SECTION (PDC)	Scratched	223.75 FS	*223.75 FS
6	1		*FRT RH WHEELARCH TRIM	Scratched	163.40 FS	*163.40 FS
7	1		*RH HEADLIGHT LED TECHNOLOGY	Scratched	2,728.95 FS	*2,728.95 FS
Total Parts (S\$)						4,313.80 4,187.90

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE FRONT BUMPER AND ATTACHMENTS	New	1,275.00	850.00
2	TO PAINTING FRONT BUMPER	New	1,038.00	986.00
3	TO CHECK ELECTRICAL WIRING SYSTEM AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENT OF HEADLIGHTS	New	177.00	168.00
4	TO REMOVE OLD PDC ASSEMBLY ,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION	New	177.00	168.00
5	TO REPLACE LEFT OR RIGHT HEADLIGHT	New	491.00	457.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,158.00</b>	<b>2,629.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >