

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22011450/RQY3E2**Date:** 06/01/2023REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNA00031052201

**Claimant Vehicle
No :** SLU4177U**Insured Vehicle
No :** GBL950X

Date of Loss: 09/11/2022

Nature of Claim: TP

Claim
No: SNM22D208104/C02/IRENEDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLU4177U**

Make & Model: VOLKSWAGEN GOLF, 1.2 TSI G12BZ (A)

Engine No: CYV515349

Reg. Date: 30/11/2017 (Man. Year: 2016)

Chassis No: WVVZZZAUZH122047

Colour: Blue

Odometer: 43386 km

Engine Capacity: 1197 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,950.21	5,996.49	2,953.72	33.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,630.00	6,670.00	4,960.00	42.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	20,580.21	12,666.49	7,913.72	38.45
+ GST 7.00/7.00% (S\$)	1,440.61	886.65	553.96	38.45
Nett Amount (S\$)	22,020.82	13,553.14	8,467.68	38.45

INSPECTION

Date of Assignment: 06/01/2023

Date Inspected: 16/11/2022 Inspected At:

Volkswagen Centre Singapore (HQ)
247 Alexandra Road
Singapore 159934

Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Jan 2023)
Parts:	144	VOLKSWAGEN GOLF 1.2 TSI G12BZ (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLU4177U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*1K WINDOW ADHESIVE	Necessary	102.88 FS	*102.88 FS
2	1		*ALL PURPOSE CLEANER	Necessary	102.88 FS	*102.88 FS
3	1		*PRIMER	Necessary	30.27 FS	*30.27 FS
4	1		*ACTIVATOR	Necessary	26.27 FS	*26.27 FS
5	1		*REAR TRUNK LID	Bent	3,184.78 FS	*3,184.78 FS
6	1		*HOOD LATCH SATIN BLACK BOOT LID LOCK	Not Necessary	266.89 FS	*- FS
7	1		*OPER.MECHAN.WITH MICRO SW	Not Necessary	802.61 FS	*- FS
8	1		*WATER DRAIN HOSE	Necessary	9.54 FS	*9.54 FS
9	1		*GASKET BOOT WEATHERSTRIP	Necessary	299.42 FS	*299.42 FS
10	1		*ADDITIONAL BRAKE LIGHT W 3RD BRAKELIGHT	Necessary	183.08 FS	*183.08 FS
11	1		*TAILLIGHT LHS TAILLIGHT INNER	Not Necessary	317.12 FS	*- FS
12	1		*INSCRIPTION BRIGHT CHROME NAME PLATE - GOLF	Necessary	89.77 FS	*89.77 FS
13	1		*INSCRIPTION BRIGHT CHROME NAME PLATE - 180 TSI	Necessary	81.11 FS	*81.11 FS
14	1		*COVER FOR BUMPER PRIMED	Deformed	1,417.50 FS	*1,417.50 FS
15	1		*REAR DIFFUSOR SATIN BLACK	Scratched	361.39 FS	*361.39 FS
16	4		*RIVET	Necessary	5.28 FS	*5.28 FS
17	1		*BUMPER REINFORCEMENT	Not Necessary	750.84 FS	*- FS
18	1		*ATTACHMENT STRIP BUMPER CTR BRACKET	Not Necessary	73.18 FS	*- FS
19	1		*GUIDE PIECE LHR BUMPER BRACKET (UPPER)	Not Necessary	43.33 FS	*- FS
20	1		*GUIDE PIECE RHR BUMPER BRACKET (UPPER)	Not Necessary	43.33 FS	*- FS
21	1		*GUIDE PIECE LHR BUMPER BRACKET (SIDE)	Not Necessary	43.33 FS	*- FS
22	1		*GUIDE PIECE RHR BUMPER BRACKET (SIDE)	Not Necessary	43.33 FS	*- FS
23	2		*LICENSE PLATE LIGHT	Not Necessary	88.74 FS	*- FS
24	1		*REFLECTOR LH	Not Necessary	81.02 FS	*- FS
25	1		*REAR NUMBER PLATE	Bent	80.00 FS	*80.00 FS
26	1		*REVERSE SENSOR	Not Necessary	400.00 FS	*- FS
27	2		*APPLICATOR	Necessary	22.32 FS	*22.32 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **8,950.21** **5,996.49**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR	New	280.00	280.00
2	B&P DIAGNOSIS AND PROGRAMMING	New	480.00	480.00
3	LABOUR	New	5,040.00	2,100.00
4	SPRAY PAINT	New	4,000.00	2,400.00
5	R&R REAR W/SCREEN	New	840.00	840.00
6	TRANSFER BOOT LID MECHANISM	New	840.00	420.00
7	REAR WATER LEAK TEST	New	150.00	150.00
Gross Labour Cost (\$\$)			11,630.00	6,670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >