

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22011454/KVY3Q2**Date:** 05/12/2022**REFERENCE**Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00085362200

**Claimant Vehicle  
No :** SLT8230C**Insured  
Vehicle No :** SJZ4346X

Date of Loss: 02/11/2022

Nature of Claim: TP

Claim  
No: SNM22D208196/C02/TOHHS**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SLT8230C**

Make &amp; Model: TOYOTA C-HR HYBRID, 1.8 E G CVT (A)

Engine No: 2ZR8204129

Reg. Date: 13/11/2017 (Man. Year: 2017)

Chassis No: ZYX102078565

Colour: Metallic Grey

Odometer: 338728 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 215/60 R17

Rear Tyre Size: 215/60 R17

Front Left Side: Arivo 6 mm

Rear Left Side: APLUS 4 mm

Front Right Side: Arivo 6 mm

Rear Right Side: APLUS 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,722.67	2,095.52	627.15	23.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,450.00	500.00	950.00	65.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>4,172.67</b>	<b>2,595.52</b>	<b>1,577.15</b>	<b>37.80</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>2,050.00</b>		
<b>Nett Amount (\$\$)</b>	<b>4,172.67</b>	<b>2,050.00</b>	<b>2,122.67</b>	<b>50.87</b>

**INSPECTION**

Date of Assignment: 15/11/2022

Date Inspected: 16/11/2022 Inspected At:

Lian Her Motors (Ang Mo Kio)  
Blk 5038, Ang Mo Kio Industrial Park 2, #01-405  
Singapore 569541

Estimated Period of Repair: 2.0 days

**Adjuster:** KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Dec 2022)
Parts:	M1-SUV	TOYOTA C-HR HYBRID 1.8 E G CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLT8230C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT GRILLE	Dented / Cut	434.80 FL	*434.80 FL
2	1		*FRONT GRILLE EMBLEM	Cracked	1,654.60 FL	*1,550.20 FL
3	1		*FRONT BUMPER	Buckled	755.70 FL	*755.70 FL
4	1		*FRONT BUMPER UPPER SPONGE	Serviceable	95.20 FL	*- FL
5	1		*FRONT BUMPER LOWER SPONGE	Serviceable	75.80 FL	*- FL
6	1		*FRONT LOWER BUMPER	Serviceable	406.10 FL	*- FL
7	1		*FRONT LOWER GRILLE	Serviceable	154.70 FL	*- FL
8	1		*FRONT NO PLATE	Dented	40.00 FS	*40.00 FS
					Sub Total (\$\$)	3,616.90 2,780.70
					- List Item Discount on L Items 25.00/25.00% (\$\$)	894.23 685.18
					Total Parts (\$\$)	2,722.67 2,095.52

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REMOVE /RENEW THE ABOVE PARTS INCLUDING KNOCKING ,WELDING & CUTTING	New	550.00	200.00
2	TO PUTTY & SPRAY PAINT ON ACCIDENT AFFECTED PORTION	New	550.00	220.00
3	REMOVE/RENEW FRONT GRILLE COLLISION SENSOR AND TO RESET TO FACTORY SPECIFICATION	New	350.00	80.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,450.00</b>	<b>500.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >