

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22011455/UVY3Q2**Date:** 07/12/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00048222200

**Claimant Vehicle
No :** SNH3948M**Insured Vehicle
No :** SKV3996K

Date of Loss: 13/11/2022

Nature of Claim: TP

Claim
No: SNM22D208195/C02/IRENE**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SNH3948M**

Make & Model: HONDA VEZEL, 1.5 (A)

Engine No: L15B3521312

Reg. Date: 15/07/2015 (Man. Year: 2015)

Chassis No: RU11021298

Colour: Red

Odometer: 121134 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Toyo 6 mm

Rear Left Side: Toyo 6 mm

Front Right Side: Toyo 6 mm

Rear Right Side: Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	28,377.96	15,798.00	12,579.96	44.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,310.00	4,580.00	1,730.00	27.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	34,687.96	20,378.00	14,309.96	41.25
Approved Total (Overridden) (\$\$)		16,000.00		
Nett Amount (\$\$)	34,687.96	16,000.00	18,687.96	53.87

INSPECTION

Date of Assignment: 05/12/2022

Date Inspected: 16/11/2022 Inspected At:

2ND Auto Pte Ltd (HQ)

15 Kaki Bukit Road 4, #01-05/53 Bartley Biz Centre
Singapore 417808

Estimated Period of Repair: 16.0 days

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Dec 2022)
Parts:	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNH3948M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,485.20 FL	*762.00 FL
2	2		*FRONT BUMPER SIDE RETAINER	Bent	144.00 FL	*70.00 FL
3	1		*FRONT CENTRE CHROME GRILLE (TOP)	Cracked	380.00 FL	*380.00 FL
4	1		*FRONT BUMPER REINFORCEMENT	Bent	550.00 FL	*316.00 FL
5	1		*FRONT HONDA BADGE	Necessary	72.00 FL	*38.00 FL
6	2		*FRONT BUMPER REINFORCEMENT BRACKETS	No such part	224.00 FL	*- FL
7	1		*FRONT BUMPER LOWER COVER	Not Necessary	178.00 FL	*- FL
8	1		*FRONT BUMPER LOWER SKIRTING	Torn	780.00 FL	*480.00 FL
9	1		*FRONT BUMPER UPPER GRILLE	Cracked	482.00 FL	*235.00 FL
10	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	352.00 FL	*- FL
11	1		*FRONT FOGLAMP	N/S Cracked	690.00 FL	*345.00 FL
12	2		*FRONT FOGLAMP GARNISH	Not Necessary	240.00 FL	*- FL
13	1		*FRONT BUMPER TOW COVER	Not Necessary	48.00 FL	*- FL
14	1		*BONNET	Buckled	1,542.00 FL	*982.00 FL
15	1		*BONNET INNER LOCK	Bent	328.00 FL	*145.00 FL
16	1		*BONNET INNER LOCK BRACKET	Cracked	72.00 FL	*72.00 FL
17	1		*FRONT BRACE PANEL CENTRE	No such part	142.00 FL	*- FL
18	1		*BONNET INNER LOCK SIDE COVER	Not Necessary	122.00 FL	*- FL
19	2		*BONNET HINGES	Bent	196.00 FL	*196.00 FL
20	1		*BONNET INSULATOR	Warped	298.00 FL	*182.00 FL
21	1		*BONNET STAND	Not Necessary	78.00 FL	*- FL
22	1		*RADIATOR	Bent	680.00 FL	*680.00 FL
23	1		*AIRCON CONDENSOR	Bent / Punctured	1,120.00 FL	*980.00 FL
24	1		*AIRCON CONDENSOR DRIER	Not Necessary	142.00 FL	*- FL
25	1		*AIRCON CONDENSOR INLET PIPE UPPER	Not Necessary	98.00 FL	*- FL
26	1		*AIRCON CONDENSOR INLET LOWER PIPE	Not Necessary	98.00 FL	*- FL
27	1		*ENGINE MANIFOLD	Not Necessary	980.00 FL	*- FL
28	1		*FRONT AIR CON FAN ASSY	Cracked / Jammed	278.00 FL	*278.00 FL
29	1		*FRONT RADIATOR FAN ASSY	Cracked / Jammed	278.00 FL	*278.00 FL
30	1		*FRONT SUPPORT PANEL CENTRE	Bent	329.00 FL	*329.00 FL
31	1		*FRONT SUPPORT PANEL COVER	Torn	292.00 FL	*292.00 FL
32	1		*LHS FRONT DOOR (NPA)	Repair	0.00 FL	*- FL
33	1		*LHS FRONT FENDER	Bent	782.00 FL	*605.00 FL
34	1		*LHS FRONT FENDER WHEEL ARCH GARNISH	Torn	280.00 FL	*280.00 FL
35	2		*RHS & LHS HEADLAMP	Cracked	2,200.00 FL	*2,200.00 FL
36	1		*TAILGATE	Badly Dented	1,420.00 FL	*953.00 FL
37	1		*TAILGATE CENTRE GARNISH	Cracked	325.00 FL	*282.00 FL
38	1		*TAILGATE INNER LOCK	Bent / Jammed	328.00 FL	*166.00 FL
39	1		*TAILGATE INNER TRIM BOARD	Distorted	342.00 FL	*208.00 FL
40	2		*TAILGATE DAMPER	Not Necessary	596.40 FL	*- FL
41	2		*TAILGATE RUBBER STOPPER	Not Necessary	11.60 FL	*- FL
42	1		*TAILGATE HONDA EMBLEM (BADGE)	Necessary	42.00 FL	*38.00 FL
43	1		*TAILGATE VEZEL EMBLEM	Necessary	98.00 FL	*65.00 FL
44	1		*TAILGATE WIPER MOTOR	Not Necessary	492.00 FL	*- FL
45	2		*TAILGATE INNER SIDE GARNISH	Not Necessary	450.00 FL	*- FL
46	1		*REAR WINDSCREEN (NPA)	Not Necessary	0.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR WINDSCREEN MOULDING	Necessary	172.00 FL	*172.00 FL
48	2		*RHS & LHS TAILGATE REFLECTOR	Cracked	1,174.00 FL	*560.00 FL
49	2		*RHS & LHS TAILLAMP	Cracked	1,964.00 FL	*970.00 FL
50	2		*RHS & LHS SIDE (CORNER) PANEL	Repair	1,164.00 FL	*- FL
51	2		*RHS & LHS WHEEL ARCH GARNISH	Torn	560.00 FL	*560.00 FL
52	1		*REAR BOOT EDGE WEATHERSTRIP	Twisted	278.00 FL	*278.00 FL
53	1		*RHS REAR FENDER	Badly Dented / Buckled	782.00 FL	*782.00 FL
54	1		*REAR BUMPER	Distorted	1,124.00 FL	*762.00 FL
55	2		*REAR BUMPER REFLECTORS	Cracked	144.00 FL	*144.00 FL
56	1		*REAR BUMPER LOWER COVER	Distorted	780.00 FL	*362.00 FL
57	1		*REAR BUMPER	Repeated	1,124.00 FL	*- FL
58	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	144.00 FL	*- FL
59	1		*REAR BUMPER LOWER COVER	Repeated	780.00 FL	*- FL
60	1		*REAR END PANEL	Badly Dented	762.00 FL	*517.00 FL
61	1		*REAR END PANEL TOP GARNISH	Twisted	261.00 FL	*162.00 FL
62	1		*REAR EXHAUST SILENCER ASSY	Bent	792.00 FL	*792.00 FL
63	1		*REAR EXHAUST SILENCER HEAT SHIELD	Bent	98.00 FL	*98.00 FL
64	1		*REAR SPARE TYRE PANEL	Crumpled / Buckled	1,245.00 FL	*911.00 FL
65	1		*REAR FLOOR PANEL TOP BOARD	Torn	278.00 FL	*278.00 FL
66	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*40.00 FS
67	1		*SET FRONT BUMPER CLIPS	Necessary	60.00 FS	*40.00 FS
68	1		*REAR WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS
69	1		*REAR TAILGATE WIPER BLADE ASSY	Not Necessary	75.00 FS	*- FS
70	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*50.00 FS
71	1		*REAR SPARE TYRE PANEL SEALANT	Not Necessary	120.00 FS	*- FS
72	1		*REAR LICENCE PLATE W/HOLDER	Not Necessary	75.00 FS	*- FS
73	1		*FRONT LICENCE PLATE W/HOLDER	Broken	75.00 FS	*40.00 FS
74	1		*SET REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
75	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	60.00 FS	*40.00 FS
76	1		*REVERSE CAMERA	Not Necessary	300.00 FS	*- FS
77	1		*SET REAR WHEEL ARCH GARNISH CLIPS	Not Necessary	60.00 FS	*- FS
78	1		*SET LHS FRONT WHEEL ARCH GARNISH CLIPS	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	35,116.20	19,635.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	6,738.24	3,837.00
Total Parts (\$\$)	28,377.96	15,798.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS, REPLACE DAMAGED PARTS AND COMPONENTS (FRONT AND REAR)	New	2,600.00	2,200.00
2	TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED & REPAIRED AREAS (FENDERS) (FRONT AND REAR)	New	2,250.00	1,800.00
3	TO REMOVE AND REFIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREAS FOR PROPER FUNCTIONS AND FOCUS HEADLAMP BEAM	New	250.00	30.00
4	TO REMOVE AND REFIX /REPLACE REAR TRIMS ,GARNISH AND FITTINGS SO AS TO FACILITATE REPAIRS AT REAR COMPARTMENT	New	200.00	80.00
5	TO REFIX REAR WINDSCREEN	New	140.00	120.00
6	TO REMOVE AND REPLACE REVERSE SENSORS /CAMERA AND CHECK FOR PROPER FUNCTION	New	120.00	50.00
7	TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS	New	240.00	120.00
8	TO REPLACE REAR EXHAUST SILENCER ASSY	New	250.00	80.00
9	TO REMOVE AND REPLACE RADIATOR /RADIATOR COOLANT	New	140.00	0.00
10	TO REMOVE AND REPLACE AIR CON CONDENSOR AND REFILL GAS	New	120.00	100.00
Gross Labour Cost (S\$)			6,310.00	4,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >