

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBF 4802X

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
2	FORK INNER TUBES (CONSISTENT)	NOT NECESSARY	440.00	-
2	FORK OUTER TUBES (CONSISTENT)	NOT NECESSARY	460.00	-
1	FORK UNDER BRACKET (CONSISTENT)	NOT NECESSARY	245.00	-
1	FRONT FENDER (CONSISTENT)	NOT NECESSARY	165.00	-
1	FRONT SIGNALS (CONSISTENT)	NOT NECESSARY	160.00	-
1	HANDLE-BAR (CONSISTENT)	BENT	220.00	220.00
1	HANDLE-BAR END (CONSISTENT)	CUT	135.00	135.00
1	SET HAND GRIP (CONSISTENT)	NOT NECESSARY	85.00	-
1	BRAKE LEVER (CONSISTENT)	CUT	125.00	115.00
2	SIDE MIRROR - R/L (CONSISTENT)	O/S CUT (1PIECE ONLY)	150.00	75.00
1	FUEL TANK SIDE COVER - R/H (CONSISTENT)	TO REPAIR SEE LABOUR	280.00	-
1	FRONT FOOTRESTS (CONSISTENT)	NOT NECESSARY	155.00	-
1	FRONT FOOTREST BRACKETS (CONSISTENT)	NOT NECESSARY	210.00	-
1	BRAKE PEDAL (CONSISTENT)	TO REPAIR SEE LABOUR	165.00	-
1	EXHAUST ASSY (CONSISTENT)	TO REPAIR SEE LABOUR	880.00	-
1	EXHAUST END CAP (CONSISTENT)	CUT	135.00	90.00
1	EXHAUST PROTECTOR (CONSISTENT)	CUT	165.00	165.00
1	SET REAR SIGNALS (CONSISTENT)	O/S CUT	160.00	70.00
1	REAR FOOTRESTS (CONSISTENT)	NOT NECESSARY	135.00	-
1	REAR FOOTREST BRACKET (CONSISTENT)	NOT NECESSARY	285.00	-
1	REAR FENDER (CONSISTENT)	DEFORMED	180.00	180.00
1	REAR TAIL LAMP (CONSISTENT)	NOT NECESSARY	355.00	-
	LESS 10% DISCOUNT		-529.00	-105.00
			4,761.00	945.00
	SPECIAL NETT ITEMS			
1	SET NUMBER PLATE (SN) (CONSISTENT)	REAR BENT	38.00	20.00
2	FORK OILS (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
2	FORK OIL SEALS (SN) (CONSISTENT)	NOT NECESSARY	56.00	-

Report Ref No. CS/ASM22011456/Uny3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

1,400.00

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	SET STEERING CONE (SN) (CONSISTENT)	NOT NECESSARY	95.00	-
1	FRONT SLIDER (SN) (CONSISTENT)	CUT	380.00	80.00
1	REAR BOX (SN) (CONSISTENT)	CUT	480.00	350.00
1	REAR BOX BRACKET (SN) (CONSISTENT)	BENT	180.00	150.00
			1,259.00	600.00
	<u>LABOUR</u>			
	TO PROVIDE TOWING SERVCE (LOD) \$50.00 (NPA)	NOT NECESSARY	-	-
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.	NOT NECESSARY	80.00	-
	TO REPAIR BODY FRAME.	NOT NECESSARY	420.00	-
	TO PROVIDE LABOUR. INCLUSIVE OF THE REPAIR OF FUEL TANK SIDE COVER - R/H, BRAKE PEDAL & EXHAUST ASSY.		480.00	280.00
			980.00	280.00
	GRAND TOTAL		7,000.00	1,825.00

Report Ref No. CS/ASM22011456/Uny3m4

RECOMMENDED COST OF LUMP SUM REPAIRS

(TO ITS PRE-ACCIDENT CONDITION)

CHUA KANG SENG

Licensed Appraiser