



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: S2M03ZQ7

Date: 30<sup>th</sup> Nov 2022

Our Ref: CS3/ASM22004006/Ewy3e2-1

**M/s Axa Insurance Pte Ltd**

8 Shenton Way #24-01

Axa Tower

Singapore 068811

(The Motor Claims Department)

Attn: Chong Arnold

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SMY 6204D**

**INSURED VEHICLE: SHB 2215D**

**ACCIDENT DATE: 25/04/2022**

We thank you for your instruction on 15/11/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SMY 6204D from M/s C L Appraiser Pte Ltd.
- b) Singapore Accident Statement of Vehicles SMY 6204D and SHB 2215D.
- c) Final Repair Bill of SMY 6204D from M/s B's Performance Pte Ltd.
- d) Colour damaged vehicle photographs of SMY 6204D.

Pre-Repair Inspection Date: 28/04/2022 at M/s B's Performance Pte Ltd, 7 Soon Lee Street Ispace #01-38, Singapore 627668.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SMY 6204D
Make & Model	: Honda Civic 1.6 VTI CVT
Year of Registration	: 2021
Chassis Number	: MRHFC5650LT000561
Engine Capacity	: 1597 cc

2. We recommend that the repairs of the entire damage require about 10 (Ten) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.