

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMW 8884M

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER (N)	CUT / DEFORMED	3,697.00	1,879.55
2	FRONT BUMPER SIDE RETAINERS @\$250.00 (N)	NOT NECESSARY	500.00	-
1	FRONT BUMPER CENTRE GRILLE (N)	NOT NECESSARY	420.00	-
1	FRONT BUMPER LOWER CENTRE GRILLE (N)	NOT NECESSARY	399.00	-
1	FRONT BUMPER SPONGE (N)	NOT NECESSARY	416.00	-
1	FRONT BUMPER REINFORCEMENT (N)	NOT NECESSARY	1,515.00	-
1	FRONT BUMPER REINFORCEMENT LOWER BRACKET (N)	NOT NECESSARY	350.00	-
1	FRONT FOG LAMP N/S (N)	NOT NECESSARY	520.00	-
1	FRONT FOG LAMP GARNISH N/S (N)	NOT NECESSARY	335.00	-
1	HEADLAMP N/S (N)	CRACKED	8,928.00	6,200.00
1	HEADLAMP NOZZLE COVER N/S (N)	NOT NECESSARY	82.00	-
1	HEADLAMP NOZZLE N/S (N)	NOT NECESSARY	350.00	-
1	FRONT AIR GUIDE TOP N/S (N)	NOT NECESSARY	98.00	-
1	FRONT FENDER N/S (N)	TO REPAIR SEE LABOUR	1,200.00	-
1	FRONT FENDER INNER SHIELD N/S (N)	NOT NECESSARY	313.00	-
1	FRONT FENDER INNER SHIELD CLIPS N/S (N)	NOT NECESSARY	50.00	-
	LESS 5% DISCOUNT		-	-403.98
			19,173.00	7,675.57
	<u>LABOUR</u>			
	TO CHECK WIRING.		50.00	20.00
	TO REFILL AIR CON GAS.	NOT NECESSARY	120.00	-
	TO SPRAY RUST PROOFING.	NOT NECESSARY	100.00	-
	TO RESET DIAGNOSTIC & REPROGRAMME SYSTEM.	NOT NECESSARY	580.00	-
	LABOUR FOR PANEL BEATING & REPLACED PARTS. INCLUSIVE OF THE REPAIR OF FRONT FENDER N/S.		500.00	300.00
	TO PUTTY & SPRAY PAINTING.		800.00	300.00
			2,150.00	620.00
	GRAND TOTAL		21,323.00	8,295.57

Report Ref No. CS/UOI22011461/Uwy3e2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		6,600.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/UOI22011461/Uwy3e2

CHUA KANG SENG

Licensed Appraiser