



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 4141T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DEFORMED	3,767.00	2,377.00
1	FRONT FENDER RIGHT	DENTED	2,163.00	1,227.00
1	FRONT HEADLAMP RIGHT	CRACKED	3,908.00	3,908.00
1	FRONT BUMPER RETAINER RIGHT	NOT NECESSARY	78.90	-
	LESS 10% DISCOUNT		-	-751.20
			9,916.90	6,760.80
	<u>LABOUR</u>			
	SPRAY PAINT WORK.		600.00	500.00
	PANEL BEATING AND LABOUR.		600.00	600.00
	TO CHECK WIRING.		100.00	30.00
	TO APPLY TUFF COAT.		150.00	50.00
	TO PERFORM DIAGNOSTIC TEST.		200.00	120.00
	TO REMOVE FRONT BUMPER SENSOR .		100.00	50.00
			1,750.00	1,350.00
	GRAND TOTAL		11,666.90	8,110.80
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,500.00

Report Ref No. CS/SMO22011462/Any3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.