



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 8445S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	TORN	650.00	650.00
1	FRONT BUMPER RETAINER LHS	SERVICEABLE	150.00	-
1	FRONT BUMPER RETAINER RHS	SERVICEABLE	150.00	-
1	BUMPER TOWING COVER	DENTED	45.00	45.00
1	FOG LAMP COVER LHS	SERVICEABLE	60.00	-
1	FOG LAMP COVER RHS	SERVICEABLE	60.00	-
1	FRONT GRILLE	MTG CRACKED	1,200.00	568.90
1	FRONT REINFORCEMENT BAR	BENT	360.00	360.00
1	FRONT BONNET	TO REPAIR SEE LABOUR	1,030.00	-
1	TOYOTA EMBLEM	NECESSARY	75.00	75.00
1	FRONT BONNET HINGE LHS	TO REPAIR SEE LABOUR	95.00	-
1	FRONT BONNET HINGE RHS	TO REPAIR SEE LABOUR	95.00	-
1	HEADLAMP LHS	SERVICEABLE	2,102.00	-
1	HEADLAMP RHS	MTG CRACKED	2,102.00	2,102.00
1	HEADLAMP BRACKET LHS	SERVICEABLE	45.00	-
1	HEADLAMP BRACKET RHS	SERVICEABLE	45.00	-
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	780.00	-
1	AIRCOND CONDENSER	SERVICEABLE	980.00	-
1	WATER RESERVOIR TANK	SERVICEABLE	290.00	-
	LESS 25% DISCOUNT		-2,578.50	-950.23
			7,735.50	2,850.67
<u>SPECIAL NETT ITEMS</u>				
1	CARPLATE WITH HOLDER (SN)	CRACKED	150.00	45.00
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	60.00	60.00
1	SET FRONT GRILLE CLIPS (SN)	NECESSARY	60.00	60.00
			270.00	165.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; REPLACE DAMAGED PARTS AND COMPONENTS. INCLUSIVE OF THE REPAIR OF FRONT BONNET, FRONT BONNET HINGE LHS, FRONT BONNET HINGE RHS AND FRONT SUPPORT PANEL.		1,200.00	400.00
	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED & REPAIRED.		1,200.00	400.00
	TO REMOVE AND RE-FIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREAS FOR PROPER FUNCTIONS.		100.00	20.00
	TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS.	NOT NECESSARY	100.00	-
	TO REMOVE AND RE-FIX FRONT AIRCOND CONDENSER AND RE-FILL GAS.	NOT NECESSARY	200.00	-
	TO REMOVE AND RE-FIX FRONT RADIATOR AND RE-FILL COOLANT.	NOT NECESSARY	180.00	-
			2,980.00	820.00
GRAND TOTAL			10,985.50	3,835.67
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,050.00

Report Ref No. CS/FCI22011463/Kqy3m4

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.