



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: CS/FCI22011463/Kqy3m4 Date: 25/04/2023  Code: FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	XE 4680A	Veh. Inspected	PC 8445S
Policy No.	D-22099559MFVS/32	Coverage (\$)	0.00
Claim No.	D22003538MFVS	Excess (\$)	0.00
Assign From	CAROLINE CABRERA	Assign Date	15/11/2022
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	TOYOTA HIACE (A)	c.c	2754
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	GDH2011020484	Colour	WHITE / GREEN
Odometer	119910 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	195 R15X8	DOUBLE KING	9 mm
L/H Front Tyre	195 R15X8	DOUBLE KING	9 mm
R/H Rear Tyre	195 R15X8	DOUBLE KING	9 mm
L/H Rear Tyre	195 R15X8	DOUBLE KING	9 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	08/11/2022	Inspection Date	15/11/2022
Survey held at	160 SIN MING DRIVE AUTOCITY #02-04 (S) 575722		
Repairer	CAR TIMES AUTOLUTION PTE LTD		
<b>5a. Remarks</b>			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	