

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS/AIS22011465/RWY3E2**Date:** 09/02/2023**REFERENCE****Insured/Claimant:** GERALD LEE YEW CHUAN(LI YOUQUAN)**Policy No:** SP2002059853**Date of Loss:** 15/11/2022**Nature of Claim:** OD **Claim No:** 202222008174**DESCRIPTION & IDENTIFICATION OF VEHICLE****Reg No:** SNF3043J**Make & Model:** MERCEDES-BENZ C200, 2.0 (A)**Engine No:** 28291480274664**Reg. Date:** 02/01/2020 (Man. Year: 2019)**Chassis No:** WDD1183872N072417**Colour:** Yellow**Odometer:** 48252 km**Engine Capacity:** 1332 cc**Market Value/New Car Price:** S\$178,000.00**Sum Insured (S\$):** **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY****General Condition:** Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes**Handbrake (Serviceable):** Yes **Engine Modification:** No **Pre-accident Condition:****CONDITION OF TYRES****Front Tyre Size:** 205/55 R16**Rear Tyre Size:** 205/55 R16**Front Left Side:** Michelin 6 mm**Rear Left Side:** Michelin 6 mm**Front Right Side:** Michelin 6 mm**Rear Right Side:** Michelin 6 mm*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,847.05	9,811.12	4,035.93	29.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,940.00	8,180.00	1,760.00	17.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	23,787.05	17,991.12	5,795.93	24.37
+ GST 7.00/7.00% (S\$)	1,665.09	1,259.38	405.71	24.37
Nett Amount (S\$)	25,452.14	19,250.50	6,201.64	24.37

INSPECTION**Date of Assignment:** 15/11/2022**Date Inspected:** 16/11/2022 **Inspected At:**

Cycle & Carriage Industries Pte Ltd (Pandan Loop)

188 Pandan Loop

Singapore 128378

Estimated Period of Repair: 10.0 days**Adjuster:** MOHD RASUL**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Feb 2023)
Parts:	143	MERCEDES-BENZ C200 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNF3043J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	15.00 FS	*15.00 FS
2	1		*SET NUMBER PLATE WITH HOUSING (REAR)		60.00 FS	*60.00 FS
3	1		*REAR BUMPER	Deformed	1,612.14 FS	*1,612.14 FS
4	1		*ELECTRICAL WIRING HARNESS	Not Necessary	160.75 FS	*- FS
5	1		*RIGHT BRACKET, BUMPER	Not Necessary	77.25 FS	*- FS
6	1		*LEFT BRACKET, BUMPER	Not Necessary	77.25 FS	*- FS
7	1		*RIGHT TAILPIPE TRIM	Cut	121.89 FS	*121.89 FS
8	1		*LEFT REFLECTING EMITTER	Not Necessary	40.87 FS	*- FS
9	1		*RIGHT REFLECTING EMITTER	Not Necessary	40.87 FS	*- FS
10	1		*LEFT COVER GRILL-TAILPIPE	Not Necessary	41.87 FS	*- FS
11	1		*RIGHT LOWER GRILL-TAILPIPE	Not Necessary	41.87 FS	*- FS
12	1		*RHR CHROME TRIM STRIP	Cut	152.42 FS	*152.42 FS
13	6		*DISTANCE SENSOR	Not Necessary	1,172.58 FS	*- FS
14	6		*SPACER RING	Necessary	42.60 FS	*42.60 FS
15	1		*LHR BASIC CARRIER FOR BUMPER	Not Necessary	103.89 FS	*- FS
16	1		*RHR BASIC CARRIER FOR BUMPER	Not Necessary	86.67 FS	*- FS
17	1		*CTR BRACKET, REAR BUMPER	Not Necessary	66.53 FS	*- FS
18	1		*CTR BASIC CARRIER FOR BUMPER	Not Necessary	100.68 FS	*- FS
19	2		*EXPANSION RIVET	Necessary	2.38 FS	*2.38 FS
20	2		*EXPANSION RIVET	Necessary	2.38 FS	*2.38 FS
21	1		*REAR BUMPER CHROME TRIM STRIP	Scratched	162.54 FS	*162.54 FS
22	1		*TRUNK LID	Bent	1,886.88 FS	*1,886.88 FS
23	2		*SPRING DAMPER	Activated	28.46 FS	*28.46 FS
24	1		*BOOT WEATHERSTRIP	Necessary	194.33 FS	*194.33 FS
25	2		*SPRING DAMPER	Activated	25.44 FS	*25.44 FS
26	1		*LHR HINGE BRACKET	Bent	289.39 FS	*289.39 FS
27	1		*RHR HINGE BRACKET	Bent	289.39 FS	*289.39 FS
28	1		*BOOT HANDLE STRIP	Not Necessary	149.88 FS	*- FS
29	1		*CLA 200 MODEL PLATE	Necessary	112.49 FS	*112.49 FS
30	1		*RELEASE HANDLE	Not Necessary	187.60 FS	*- FS
31	1		*MERCEDES STAR	Necessary	164.74 FS	*164.74 FS
32	1		*LOCK	Not Necessary	333.55 FS	*- FS
33	1		*STRIKER	Not Necessary	23.69 FS	*- FS
34	1		*REAR END PANEL	Bent	1,146.08 FS	*1,146.08 FS
35	1		*CROSSMEMBER, REAR	Bent	478.34 FS	*478.34 FS
36	1		*LOAD COMPARTMENT WELL	Not Necessary	774.67 FS	*- FS
37	1		*REAR UNDER COVER, SUBSTRUCTURE	Cracked	166.09 FS	*166.09 FS
38	1		*LH REAR LAMP COMBINATION	Scratched	713.21 FS	*713.21 FS
39	1		*RH/ REAR LAMP COMBINATION	Scratched	713.21 FS	*713.21 FS
40	1		*BOOT LEFT REAR LAMP COMBINATION	Scratched	555.46 FS	*555.46 FS
41	1		*BOOT RIGHT REAR LAMP COMBINATION	Not Necessary	555.46 FS	*- FS
42	1		*REAR LOWER BUMPER	Deformed	558.10 FS	*558.10 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*BLIND RIVET W CSK.HEAD (30PCS)	Necessary	60.30 FS	*60.30 FS
44	1		*CTR BASIC CARRIER FOR BUMPER	Bent	100.68 FS	*100.68 FS
45	1		*LHR BUMPER TRIM STRIP	Cracked	152.42 FS	*152.42 FS
46	4		*EXPANSION RIVET	Necessary	4.76 FS	*4.76 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					13,847.05	9,811.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD	New	380.00	380.00
2	CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE	New	120.00	120.00
3	REMOVE AND TRANSFER REAR BOOT COMPONENT TO NEW PANEL	New	480.00	480.00
4	REMOVE & REFIT LUGGAGE COMPARTMENT, TRIM, GARNISH CARPET FOR NECESSARY REPAIR	New	960.00	960.00
5	PANEL BEAT TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH	New	4,800.00	3,840.00
6	RESPRAY ON REAR BUMPER, BOOT, END PANEL AND ACCIDENT AFFECTED AREA	New	3,200.00	2,400.00
Gross Labour Cost (S\$)			9,940.00	8,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >