



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YP 3793U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER (N)	BENT	1,600.00	1,485.82
2	FRONT BUMPER BRACKET @\$327.13 (N)	TO REPAIR SEE LABOUR	654.26	-
2	HEADLAMP @\$1610.00 (N)	NOT NECESSARY	3,220.00	-
2	HEADLAMP TRIM @\$165.00 (N)	NOT NECESSARY	330.00	-
2	HEADLAMP BRACKET @\$165.00 (N)	NOT NECESSARY	330.00	-
2	FRONT BUMPER FOG LAMP @\$220.06 (N)	NOT NECESSARY	440.12	-
2	FRONT BUMPER FOG LAMP BRACKET @\$130.00 (N)	NOT NECESSARY	260.00	-
10	FRONT GRILLE CLIPS @\$5.00 (N)	NOT NECESSARY	50.00	-
1	BONNET (N)	DENTED	3,500.00	3,011.69
2	FRONT CORNER PANEL @\$912.26 (N)	NOT NECESSARY	1,824.52	-
2	FRONT CORNER PANEL SIGNAL LAMP @\$120.00 (N)	NOT NECESSARY	240.00	-
1	FRONT BUMPER REINFORCEMENT (N)	BENT	720.00	720.00
1	FRONT PANEL (N)	BADLY DENTED	1,600.00	1,600.00
1	FRONT WINDSCREEN GLASS (N)	CRACKED	2,657.90	1,600.00
1	FRONT WINDSCREEN MOULDING (N)	TWISTED	95.00	95.00
1	AUDIO ANTENA (N) (DAMAGED)	NOT CONSISTENT WITH THE IMPACT	180.00	-
1	AIRCON CONDENSER PRESSURE PIPE (N)	NOT NECESSARY	150.00	-
1	AIRCON CONDENSER HIGH PRESSURE PIPE (N)	NOT NECESSARY	150.00	-
1	RADIATOR SPARE TANK (N)	DEFORMED	450.00	245.00
1	FRONT GRILLE (N) }	CRACKED	1,500.00	1,500.00
1	FRONT GRILLE EMBLEM BADGE (N) }		160.00	-
1	FRONT GRILLE FIGHTER BADGE (N) }		120.00	-
1	WIPER MOTOR (N)	NOT NECESSARY	580.00	-
2	WIPER LINKAGE @\$220.00 (N)	BENT	440.00	440.00
2	WIPER ARM @\$80.00 (N)	BENT	160.00	160.00
1	WIPER BLADE (N)	BENT	60.00	60.00
1	DASHBOARD (N)	CUT / TORN	2,600.00	2,200.00
1	DASHBOARD REINFORCEMENT (N)	NOT NECESSARY	1,100.00	-
1	DASHBOARD CENTER TOP COVER (N)	NOT NECESSARY	450.00	-
1	DASHBOARD CENTER COVER (N)	NOT NECESSARY	620.00	-
1	DASHBOARD CONSOLE LEFT (N)	NOT NECESSARY	550.00	-
1	DASHBOARD LOWER COVER (N)	NOT NECESSARY	280.00	-

Report Ref No. CS/LAW22011466/Uwy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	STEERING COLUMN TOP COVER (N)	NOT NECESSARY	220.00	-
1	STEERING COLUMN BOTTOM COVER (N)	NOT NECESSARY	220.00	-
1	AIRCON BLOWER UNIT (N)	CRACKED	1,800.00	1,800.00
1	COOLING COIL (N)	NOT NECESSARY	2,600.00	-
2	FRONT PANEL OUTER HANDLE @\$160.00 (N)	O/S DAMAGED	320.00	160.00
2	FRONT PANEL OUTER HANDLE BRACKET @\$240.00 (N)	NOT NECESSARY	480.00	-
2	FRONT PANEL OUTER HANDLE COVER @\$40.00 (N)	O/S MISSING	80.00	40.00
1	FRONT BONNET EMBLEM (N)	NECESSARY	140.00	140.00
1	BONNET LOCK (N)	TWISTED	180.00	180.00
	LESS 10% DISCOUNT		-3,311.18	-
	LESS 25% DISCOUNT		-	-3,859.38
			29,800.62	11,578.13
	<u>SPECIAL NETT ITEMS</u>			
1	I.U. BRACKET (SN)	NECESSARY	30.00	20.00
			30.00	20.00
	<u>LABOUR</u>			
	TO REMOVE AND REFIT FRONT WINDSCREEN GLASS.		300.00	150.00
	TO DISMANTLE AND REFIT INSTRUMENT DASHBOARD, CHECK ELECTRICAL LIGHTINGS AND RE-RUN, RE-ROUTE WIRE HARNESS.		450.00	200.00
	TO DISMANTLE AIR-CON ASSY, REMOVE AND RENEWAL OF PARTS, VACUUM AND CHARGE-IN GAS.		180.00	100.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		250.00	30.00
	TOWING CHARGES.		450.00	180.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		300.00	60.00
	TO REMOVE AND REPLACE FRONT WIPER MOTOR AND LINKAGE.	NOT NECESSARY	250.00	-
	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF FRONT BUMPER BRACKET.		3,500.00	1,100.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		1,800.00	700.00
			7,480.00	2,520.00
	GRAND TOTAL		37,310.62	14,118.13

Report Ref No. CS/LAW22011466/Uwy3e2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			11,200.00
---	--	--	-----------

Report Ref No. CS/LAW22011466/Uwy3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.